Manhole Inspection Report



Date:

Customer:

05/16/2018

Weather:

Cert. #:

Coding:

RZMACP

MH#:

M-704-067

Owner: NA

Len. Surveyed: 8.6

P.O.#:

Surveyor:

Jen Costello U-907-5518

Rim to Invert: Wall Material:

9.3 Concrete

(reinforced)

Street:

Edgewater Dr. 478' South of Fox Trail Project:

Hobart, IN

City:

GPS Northing:

2905719.616

Location:

GPS Easting:

2905719.616

Drain Area:

GPS Accuracy:

Sub-Meter

Cover Shape:

North Circular

Hobart, IN

Evidence of Surcharge: No

Cover Size:

22.5

Potential for Runoff:

2100

None

Comments:

O&M Index:

2.00 0.00

2.00

O&M Quick:

Structural Quick:

2100 O&M Rating: 0000 Structural Rating:

2.00 0.00

Structural Index: Overall Index:


Overall Quick:

Overall Rating:

2.00

Position	Code	Observation	Video (sec)	Grade
л-704-067				
.0	MGP	General Photo	10	NA
.9	MGO	General Observation	25	NA
8.6	DSF	Deposits Settled Fine	54	M 2
8.6	MGO	General Observation	65	NA
Camera Direction				


Code:



Description: **General Photo** Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Step: NO Remarks: **ACCESS MH**

MGP

Wednesday, May 3, 2023 2



Code: MGO

Description: General Observation

Distance (ft): .9
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: UNDERSIDE OF FRAME



Code: **DSF**

Description: Deposits Settled Fine

Distance (ft): 8.6
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 12
Clock To: 6
1st Value:

Value Percent: 5.000 Step: NO

Remarks:

Code:

2nd Value:

Description: General Observation

MGO



Distance (ft): **8.6**Structural Grade: **0**

O&M Grade: **0**

Clock Start/From: Clock To:

1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: END SURVEY

Wednesday, May 3, 2023