## **Manhole Inspection Report**



Date:

05/16/2018

Weather:

Cert. #:

Coding:

**RZMACP** 

MH#:

M-704-070

Owner: NA Len. Surveyed: 3.1

P.O.#:

Surveyor: Jen Costello Rim to Invert:

Concrete Wall Material:

(reinforced)

Street: City:

Customer:

East of Lake Park Ave. 634'. West of Project:

U-907-5518

Hobart, IN

Location:

Hobart, IN

**GPS Northing:** 

2905074.751

North

GPS Easting:

2905074.751

Drain Area: Cover Shape:

GPS Accuracy:

**Sub-Meter** 

Cover Size:

Circular

Evidence of Surcharge: No

22.5

Potential for Runoff: None

Comments:

O&M Index:

2.00 0.00

O&M Quick: Structural Quick:

2100 0000 2100

O&M Rating: Structural Rating:

Overall Rating:

2.00 0.00 2.00

Structural Index: Overall Index:

2.00 Overall Quick:

Wednesday, May 3, 2023

Position	Code	Observation	Video (sec)	Grade
-704-070				
.0	MGP	General Photo	10	NA
1.4	MGO	General Observation	27	NA
3.1	DSF	Deposits Settled Fine	43	M 2
3.1	MGO	General Observation	55	NA

Code:



Description:	General Photo	
Dietaras (ft).	0	
Distance (ft):	.0	
Structural Grade:	0	
O&M Grade:	0	
Clock Start/From:		
Clock To:		
1st Value:		
2nd Value:		
Value Percent:		
Step:	NO	
Remarks:	ACCESS MH	

MGP

Wednesday, May 3, 2023 2



Code: MGO

Description: General Observation

Distance (ft): 1.4
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:

Step: NO

Remarks: UNDERSIDE OF FRAME



Code: **DSF** 

Description: Deposits Settled Fine

Distance (ft): 3.1
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 12
Clock To: 12
1st Value:

2nd Value:

Value Percent: 5.000 Step: NO

Remarks:



Code: MGO

Description: General Observation

Distance (ft): 3.1
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: END SURVEY

Wednesday, May 3, 2023