Manhole Inspection Report

Date:	04/28/2018	Weather:		Coding:	RZMACP
MH#:	M-705-017	Owner:	NA	Len. Surveyed:	-
P.O.#:		Surveyor:	Jen Costello	Rim to Invert:	9.9
Customer:		Cert. #:	U-907-5518	Wall Material:	Brick
Street:	Intersection of 6th	St. and Main St.	Project:	Hobart, IN	
City:	Hobart, IN		GPS Northing:	41.52898407	
Location:			GPS Easting:	-87.25325012	
Drain Area:	South		GPS Accuracy:	Nearest Meter	
Cover Shape:	Circular		Evidence of Surcharge:	No	
Cover Size:	22.5		Potential for Runoff:	None	
Comments:					
O&M Index:	2.00	O&M Quick:	2100	O&M Rating:	2.00
Structural Index:	3.00	Structural Qui	ck: 3100	Structural Rating:	3.00
Overall Index:	2.50	Overall Quick	3121	Overall Rating:	5.00

RedZone

	Position	Code	Observation	Video (sec)	Grade
M-705-01	7				
\leq	.0	MGO	General Observation	10	NA
	.0	DB	Displaced Brick	21	S 3
	1.9	MGP	General Photo	38	NA
	6.7	MGO	General Observation	61	NA
	8.0	DSF	Deposits Settled Fine	75	M 2
	9.4	MGO	General Observation	89	NA
Camera Direction					





Code: Description:	DB Displaced Brick
Distance (ft):	.0
Structural Grade:	3
O&M Grade:	0
Clock Start/From:	12
Clock To:	12
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	



Code: Description:	MGP General Photo
Distance (ft): Structural Grade: O&M Grade: Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Step: Remarks:	1.9 0 0 NO UNDERSIDE OF FRAME
Remarks.	ONDERGIDE OF FRAME



Code:	MGO
Description:	General Observation
Distance (ft):	6.7
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	BROKEN STEP



Code:DSFDescription:Deposits Settled Fine

Distance (ft):	8.0
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	12
Clock To:	12
1st Value:	
2nd Value:	
Value Percent:	5.000
Step:	NO
Remarks:	



Code:	MGO
Description:	General Observation
Distance (ft):	9.4
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	END SURVEY