Manhole Inspection Report



Date: 05/03/2018

Weather:

NA

Coding:

RZMACP

MH#: P.O.#:

M-705-032

Owner:

Jen Costello

Len. Surveyed: 8.8 Rim to Invert:

Customer:

Cert. #:

Surveyor:

U-907-5518

Wall Material:

Concrete (reinforced)

Street: City:

Center St. 185' North of 4th St.

Project: **GPS Northing:**

Hobart, IN 41.53206635

Location:

Drain Area:

South

GPS Easting:

-87.25341797

Cover Shape:

Circular

Hobart, IN

GPS Accuracy: Evidence of Surcharge:

Nearest Meter

Cover Size:

22.5

No Potential for Runoff: None

Comments:

0.00	O&M Quick

0000 O&M Rating. 0.00

O&M Index: Structural Index: Overall Index:

		Odivi Quick.		Octivi Nating.	
x:	0.00	Structural Quick:	0000	Structural Rating:	0.00
	0.00	Overall Quick:	0000	Overall Rating:	0.00
		_			

1 Wednesday, May 3, 2023

Position	Code	Observation	Video (sec)	Grade
л- 7 05-032				
.0	MGO	General Observation	10	NA
1.4	MGO	General Observation	27	NA
8.8	MGO	General Observation	55	NA
Camera Direction				



Code: MGO
Description: General Observation

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0
Clock Start/From:
Clock To:
1st Value:
2nd Value:
Value Percent:
Step: NO

Remarks: ACCESS MH



Code: MGO

Description: General Observation

Distance (ft): 1.4
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: UNDERSIDE OF FRAME





Code: MGO

Description: General Observation

Distance (ft): 8.8
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: END SURVEY

Wednesday, May 3, 2023 3