## **Manhole Inspection Report**

| Date:             | 05/03/2018                   | Weather:      |                        | Coding:            | RZMACP |
|-------------------|------------------------------|---------------|------------------------|--------------------|--------|
| MH#:              | M-705-054                    | Owner:        | NA                     | Len. Surveyed:     | 6.5    |
| P.O.#:            |                              | Surveyor:     | Jen Costello           | Rim to Invert:     | 6.8    |
| Customer:         |                              | Cert. #:      | U-907-5518             | Wall Material:     | Brick  |
| Street:           | 3rd St. 36' East of Park St. |               | Project:               | Hobart, IN         |        |
| City:             | Hobart, IN                   |               | GPS Northing:          | 41.53092575        |        |
| Location:         |                              |               | GPS Easting:           | -87.25806427       |        |
| Drain Area:       | West                         |               | GPS Accuracy:          | Nearest Meter      |        |
| Cover Shape:      | Circular                     |               | Evidence of Surcharge: | Νο                 |        |
| Cover Size:       | 22.5                         |               | Potential for Runoff:  | None               |        |
| Comments:         |                              |               |                        |                    |        |
| O&M Index:        | 0.00                         | O&M Quick:    | 0000                   | O&M Rating:        | 0.00   |
| Structural Index: | 3.00                         | Structural Qu | ick: 3100              | Structural Rating: | 3.00   |
| Overall Index:    | 3.00                         | Overall Quick | c <b>3100</b>          | Overall Rating:    | 3.00   |

RedZone

|                  | Position | Code | Observation           | Video (sec) | Grade |
|------------------|----------|------|-----------------------|-------------|-------|
| M-705-05         | 4        |      |                       |             |       |
| $\sim$           | .0       | MGO  | General Observation   | 10          | NA    |
|                  | .0       | FL   | Fracture Longitudinal | 21          | S 3   |
|                  | 1.7      | MGO  | General Observation   | 38          | NA    |
|                  | 4.5      | MGO  | General Observation   | 58          | NA    |
|                  | 6.5      | MGO  | General Observation   | 74          | NA    |
| Camera Direction |          |      |                       |             |       |



| Code:<br>Description: | MGO<br>General Observation |
|-----------------------|----------------------------|
| Distance (ft):        | .0                         |
| Structural Grade:     | 0                          |
| O&M Grade:            | 0                          |
| Clock Start/From:     |                            |
| Clock To:             |                            |
| 1st Value:            |                            |
| 2nd Value:            |                            |
| Value Percent:        |                            |
| Step:                 | NO                         |
| Remarks:              | ACCESS MH                  |



Code:FLDescription:Fracture LongitudinalDistance (ft):.0Structural Grade:3O&M Grade:0Clock Start/From:8Clock To:.11st Value:.22nd Value:.

Value Percent:

Step:

Remarks:




| Code:<br>Description: | MGO<br>General Observation |
|-----------------------|----------------------------|
| Distance (ft):        | 1.7                        |
| Structural Grade:     | 0                          |
| O&M Grade:            | 0                          |
| Clock Start/From:     |                            |
| Clock To:             |                            |
| 1st Value:            |                            |
| 2nd Value:            |                            |
| Value Percent:        |                            |
| Step:                 | NO                         |
| Remarks:              | UNDERSIDE OF FRAME         |
|                       |                            |

NO



| Code:             | MGO                 |
|-------------------|---------------------|
| Description:      | General Observation |
|                   |                     |
|                   |                     |
| Distance (ft):    | 4.5                 |
| Structural Grade: | 0                   |
| O&M Grade:        | 0                   |
| Clock Start/From: |                     |
| Clock To:         |                     |
| 1st Value:        |                     |
| 2nd Value:        |                     |
| Value Percent:    |                     |
| Step:             | YES                 |
| Remarks:          | BROKEN STEP         |



Code:MGODescription:General Observation

| Distance (ft):    | 6.5        |
|-------------------|------------|
| Structural Grade: | 0          |
| O&M Grade:        | 0          |
| Clock Start/From: |            |
| Clock To:         |            |
| 1st Value:        |            |
| 2nd Value:        |            |
| Value Percent:    |            |
| Step:             | NO         |
| Remarks:          | END SURVEY |