Manhole Inspection Report



Date: 09/25/2022 Weather: Coding: RZMACP

 MH#:
 M-705-055
 Owner:
 NA
 Len. Surveyed:
 8.4

 P.O.#:
 Surveyor:
 Jen Costello
 Rim to Invert:
 9.5

 Customer:
 Cert. #:
 U-907-5518
 Wall Material:
 Brick

Street:3rd St. 258' East of S. Lake Park Ave.Project:Hobart, INCity:Hobart, INGPS Northing:2288597.54

Location:Local Rural StreetsGPS Easting:2904725.128Drain Area:WestGPS Accuracy:Sub-Meter

Cover Shape: Circular Evidence of Surcharge: No
Cover Size: 24.0 Potential for Runoff: None

Comments:

O&M Index:	2.50	O&M Quick:	3121	O&M Rating:	5.00
Structural Index:	0.00	Structural Quick:	0000	Structural Rating:	0.00
Overall Index:	2.50	Overall Quick:	3121	Overall Rating:	5.00

Position	Code	Observation	Video (sec)	Grade
-705-055				
.0	MGO	General Observation	10	NA
0.	ISGT	Intruding Sealing Grout	21	M 3
2.6	MGO	General Observation	40	NA
8.4	DSGV	Deposits Settled Gravel	65	M 2
8.4	MGO	General Observation	77	NA

Code:



Description:	General Observation	
Distance (ft):	.0	
Structural Grade:	0	
O&M Grade:	0	
Clock Start/From:		
Clock To:		
1st Value:		
2nd Value:		
Value Percent:		
Step:	NO	
Remarks:	access mh	

MGO



Code: ISGT

Description: Intruding Sealing Grout

Distance (ft): .0
Structural Grade: 0
O&M Grade: 3
Clock Start/From: 8
Clock To: 12

1st Value: 2nd Value:

Value Percent: 20.000 Step: NO

Remarks:



Code: MGO

Description: General Observation

Distance (ft):

Structural Grade:

O&M Grade:

Clock Start/From:

Clock To:

1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: underside of frame



Code: **DSGV**

Description: Deposits Settled Gravel

Distance (ft): 8.4
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 12
Clock To: 12
1st Value:

2nd Value: Value Percent: Step:

5.000 NO

Remarks:



Code: MGO

Description: General Observation

Distance (ft): 8.4
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: end of survey