## **Manhole Inspection Report**



Date: 05/03/2018 Weather: Coding: RZMACP

 MH#:
 M-705-087
 Owner:
 NA
 Len. Surveyed:
 4.8

 P.O.#:
 Surveyor:
 Jen Costello
 Rim to Invert:
 5.4

 Customer:
 Cert. #:
 U-907-5518
 Wall Material:
 Brick

Street: On 3rd St. 243' West of Main St. Project: Hobart, IN

City: Hobart, IN GPS Northing: 41.53178406
Location: GPS Easting: -87.2556076

Drain Area: South GPS Accuracy: Nearest Meter

Cover Shape: Circular Evidence of Surcharge: No
Cover Size: Potential for Runoff: None


Comments:

O&M Index:	0.00	O&M Quick:	0000	O&M Rating:	0.00
Structural Index:	0.00	Structural Quick:	0000	Structural Rating:	0.00
Overall Index:	0.00	Overall Quick:	0000	Overall Rating:	0.00

Wednesday, May 3, 2023

	Position	Code	Observation	Video (sec)	Grade
M-705-08	7				
	0	MGO	General Observation	10	NA
- 11	1.5	MGO	General Observation	27	NA
- 11	4.8	MGO	General Observation	47	NA
Camera Direction					

Code:



Description: **General Observation** Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Step: NO Remarks: access mh

MGO

Wednesday, May 3, 2023 2



Code: MGO

Description: General Observation

Distance (ft): 1.5
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: underside of frame



Code: MGO

Description: General Observation

Distance (ft): 4.8
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: end survey

Wednesday, May 3, 2023 3