
Manhole Inspection Report						
Date:	04/24/2018	Weather:		Coding:	RZMACP	
MH#:	M-706-001	Owner:	NA	Len. Surveyed	: 17.4	
P.O.#:		Surveyor:	Jen Costello	Rim to Invert:	16.8	
Customer:	8.7	Cert. #:	U-907-5518	Wall Material:	Concrete (reinforced)	
Street:	Intersection of Linda St. and 10th St. Project: Hobart, IN					
City:	Hobart, IN		GPS Northing:	0.0		
Location:			GPS Easting:	0.0		
Drain Area:	Southeast		GPS Accuracy:	Nearest Meter		
Cover Shape:	Circular		Evidence of Surcharge:	No		
Cover Size: Comments:	22.5	I	Potential for Runoff:	None		
O&M Index:	2.00	O&M Quick:	2100	O&M Rating:	2.00	
Structural Index:	0.00	Structural Qui		Structural Rating:	0.00	
Overall Index:	2.00	Overall Quick:		Overall Rating:	2.00	

Positio	on Code	Observation	Video (sec)	Grade
706-001				
.0	MGO	General Observation	10	NA
2.1	MGP	General Photo	27	NA
15.9	DAGS	Deposits Attached Grease	68	M 2
17.4	MGO	General Observation	83	NA



Code: Description:	MGO General Observation
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	ACCESS MH



Code: MGP Description: **General Photo** Distance (ft): 2.1 Structural Grade: 0 O&M Grade: 0 Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Step: NO Remarks: UNDERSIDE OF FRAME

DAGS

Deposits Attached Grease



Distance (ft):	15.9
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	12
Clock To:	12
1st Value:	
2nd Value:	
Value Percent:	5.000
Step:	NO
Remarks:	

Code:

Description:



Code:	MGO
Description:	General Observation
Distance (ft):	17.4
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	END SURVEY