

Manhole Ins	spection Repor	t			RedZor
Date:	04/23/2018	Weather:		Coding:	RZMACP
MH#:	M-706-008.4	Owner:	NA	Len. Surveyed	5.3
P.O.#:		Surveyor:	Jen Costello	Rim to Invert:	4.9
Customer:	8.7	Cert. #:	U-907-5518	Wall Material:	Concrete (reinforced)
Street:	9th St. 167' East of	Garfield St.	Project:	Hobart, IN	
City:	Hobart, IN		GPS Northing:	0.0	
Location:			GPS Easting:	0.0	
Drain Area:	Southeast		GPS Accuracy:	Nearest Meter	
Cover Shape:	Circular		Evidence of Surcharge:	Νο	
Cover Size:	22.5		Potential for Runoff:	None	
Comments:					
O&M Index:	2.00	O&M Quick:	2100	O&M Rating:	2.00
Structural Index:	3.00	Structural Qu	uick: 3100	Structural Rating:	3.00
Overall Index:	2.50	Overall Quic	k: <b>3121</b>	Overall Rating:	5.00

MGO General Observation MGO General Observation MGO General Observation DAE Deposits Attached Encrus MMC Material Change SAV Surface Aggregate Visible MGO General Observation	64	NA NA NA M 2 NA S 3 NA
MGOGeneral ObservationMGOGeneral ObservationDAEDeposits Attached EncrusMMCMaterial ChangeSAVSurface Aggregate Visible	21 38 tation 51 64 75	NA NA M 2 NA S 3
MGO General Observation DAE Deposits Attached Encrus MMC Material Change SAV Surface Aggregate Visible	38 tation 51 64 75	NA M 2 NA S 3
DAE Deposits Attached Encrus MMC Material Change SAV Surface Aggregate Visible	tation 51 64 75	M 2 NA S 3
MMC Material Change SAV Surface Aggregate Visible	64 75	NA S 3
SAV Surface Aggregate Visible	75	S 3
MGO General Observation	92	NA



Code: Description:	MGO General Observation
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	ACCESS MH

\_\_\_\_



Code: Description:	MGO General Observation
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	MISSING STEOS

Code:



Description:	General Observation
Distance (ft):	1.6
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	UNDERSIDE OF FRAME

MGO



Code: Description:	DAE Deposits Attached Encrustation
Distance (ft):	1.6
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	1
Clock To:	5
1st Value:	
2nd Value:	
Value Percent:	5.000
Step:	NO
Remarks:	



Code: Description: MMC Material Change

Distance (ft):	2.5
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	CONCRETE BLOCK



Code: Description:	SAV Surface Aggregate Visible
Distance (ft):	2.5
Structural Grade:	3
O&M Grade:	0
Clock Start/From:	12
Clock To:	12
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	



MGO
General Observation
5.2
0
0
NO
END SURVEY