## **Manhole Inspection Report**



Date: 04/23/2018 Weather: Coding: RZMACP

 MH#:
 M-706-008.5
 Owner:
 NA
 Len. Surveyed:
 4.2

 P.O.#:
 Surveyor:
 John Kuglmaier
 Rim to Invert:
 4.1

Customer: 8.7 Cert. #: U-1215-07002349 Wall Material: Concrete

(reinforced)

Street: 384' South of 9th St. East of Garfield Project: Hobart, IN

City: Hobart, IN GPS Northing: 0.0

Location: GPS Easting: **0.0** 

Drain Area: Southeast GPS Accuracy: Nearest Meter

Cover Shape: Circular Evidence of Surcharge: Yes
Cover Size: Potential for Runoff: None

Comments:

O&M Index:	2.00	O&M Quick:	2100	O&M Rating:	2.00
Structural Index:	0.00	Structural Quick:	0000	Structural Rating:	0.00
Overall Index:	2.00	Overall Quick:	2100	Overall Rating:	2.00

Wednesday, May 3, 2023

Position	Code	Observation	Video (sec)	Grade
6-008.5				
.0	MGP	General Photo	10	NA
2.1	MGP	General Photo	28	NA
2.3	MGO	General Observation	42	NA
2.3	DSF	Deposits Settled Fine	53	M 2
3.6	MGO	General Observation	67	NA



Description:	General Photo
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	

MGP

Wednesday, May 3, 2023

Code:



Code: **MGP** 

Description: **General Photo** 

Distance (ft): 2.1 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks:



Code: MGO

Description: **General Observation** 

Distance (ft): 2.3 Structural Grade: 0 0 O&M Grade: Clock Start/From: Clock To:

1st Value: 2nd Value: Value Percent:

NO Step:

Remarks: Surcharge



Code: DSF

**Deposits Settled Fine** Description:

Distance (ft): 2.3 Structural Grade: 0 O&M Grade: 2 Clock Start/From: 12 Clock To: 12 1st Value:

2nd Value:

Value Percent: 10.000 Step: NO

Remarks:

Wednesday, May 3, 2023 3



Code: MGO

Description: General Observation

Distance (ft): 3.6
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: Ins. Comp.

Wednesday, May 3, 2023 4