

Manhole Ins	spection Repor	t			RedZor
Date:	04/24/2018	Weather:		Coding:	RZMACP
MH#:	M-706-010.2	Owner:	NA	Len. Surveyed	: 7.9
P.O.#:		Surveyor:	Jen Costello	Rim to Invert:	8.1
Customer:	8.7	Cert. #:	U-907-5518	Wall Material:	Concrete (reinforced)
Street:	Lake St. 409' South	of 8th St.	Project:	Hobart, IN	
City:	Hobart, IN		GPS Northing:	0.0	
Location:			GPS Easting:	0.0	
Drain Area:	Southeast		GPS Accuracy:	Nearest Meter	
Cover Shape:	Circular		Evidence of Surcharge:	No	
Cover Size: Comments:	22.5		Potential for Runoff:	None	
O&M Index:	0.00	O&M Quick:	0000	O&M Rating:	0.00
Structural Index:	4.50	Structural Qu	uick: 5141	Structural Rating:	9.00
Overall Index:	4.50	Overall Quic	k: 5141	Overall Rating:	9.00

	Code	Observation	Video (sec)	Grade
706-010.2				
.0	MGO	General Observation	10	NA
2.0	FM	Fracture Multiple	27	S 4
/2.0	MGO	General Observation	38	NA
3.5	SRV	Surface Reinforcement Visible	54	S 5
7.9	MGO	General Observation	75	NA




Code: Description:	MGO General Observation
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	ACCESS MH



Code:	FM
Description:	Fracture Multiple
Distance (ft):	2.0
Structural Grade:	4
O&M Grade:	0
Clock Start/From:	9
Clock To:	11
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	

__ _

.



Code: Description:	MGO General Observation
Distance (ft): Structural Grade: O&M Grade: Clock Start/From: Clock To: 1st Value:	2.0 0 0
2nd Value: Value Percent: Step: Remarks:	NO UNDERSIDE OF FRAME



Code: Description:	SRV Surface Reinforcement Visible
Description.	Surface Reinforcement Visible
Distance (ft):	3.5
Structural Grade:	5
O&M Grade:	0
Clock Start/From:	2
Clock To:	4
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	



Code: Description: MGO General Observation

Distance (ft):	7.9
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	END SURVEY