## **Manhole Inspection Report**



Date: 04/23/2018 Weather: Coding: RZMACP

 MH#:
 M-706-011.5
 Owner:
 NA
 Len. Surveyed:
 7.3

 P.O.#:
 Surveyor:
 Jen Costello
 Rim to Invert:
 7.3

 Customer:
 8.7
 Cert. #:
 U-907-5518
 Wall Material:
 Brick

Street: Lake St. 504' North of 10th St. Project: Hobart, IN

City: Hobart, IN GPS Northing: 0.0 Location: GPS Easting: 0.0

Drain Area: Southeast GPS Accuracy: Nearest Meter

Cover Shape: Circular Evidence of Surcharge: No
Cover Size: Potential for Runoff: None

Comments:

O&M Index:	2.00	O&M Quick:	2100	O&M Rating:	2.00
Structural Index:	4.00	Structural Quick:	4100	Structural Rating:	4.00
Overall Index:	3.00	Overall Quick:	4121	Overall Rating:	6.00

	Position	Code	Observation	Video (sec)	Grade
M-706-01	1.5				
	<u> </u>	MGO	General Observation	10	NA
	\3	MB	Missing Brick	22	S 4
- 11	2.3	MGP	General Photo	40	NA
- 11	6.4	OBR	Obstacle Rocks	62	M 2
- 11	7.3	MGO	General Observation	75	NA
Camera Direction					



**General Observation** Description: Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: NO Step: Remarks: **ACCESS** mh

MGO

Code:



Code: MB


Description: Missing Brick

Distance (ft): .3
Structural Grade: 4
O&M Grade: 0
Clock Start/From: 3
Clock To: 9
1st Value:

1st Value: 2nd Value: Value Percent:

Step: NO

Remarks:



Code: MGP

Description: General Photo

Distance (ft): 2.3
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: underside of frame



Code: OBR

Description: Obstacle Rocks

5.000

NO

Distance (ft): 6.4
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 6
Clock To:
1st Value:

2nd Value: Value Percent: Step:

Remarks:



Code: MGO

Description: General Observation

Distance (ft): 7.3
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: end survey