Manhole Inspection Report



Date: 04/23/2018 Weather: Coding: RZMACP

M-706-013.6 MH#: Owner: NA Len. Surveyed: 9.0 P.O.#: Surveyor: Jen Costello Rim to Invert: 8.8 Customer: 8.7 U-907-5518 Wall Material: **Brick** Cert. #:

Street: Intersection of 10th St. and Water St Project: Hobart, IN

City: Hobart, IN GPS Northing: 0.0

Location: GPS Easting: **0.0**

Drain Area: Southeast GPS Accuracy: Nearest Meter

Cover Shape: Circular Evidence of Surcharge: No
Cover Size: Potential for Runoff: None

Comments:

6.00 3.00 4121 O&M Rating: O&M Index: O&M Quick: 3.00 3100 3.00 Structural Index: Structural Quick: Structural Rating: 9.00 Overall Index: 3.00 Overall Quick: Overall Rating:

Wednesday, May 3, 2023

Position	Code	Observation	Video (sec)	Grade
06-013.6				
.0	MGO	General Observation	10	NA
2.0	MGP	General Photo	27	NA
2.0	SAV	Surface Aggregate Visible	40	S 3
7.4	DSF	Deposits Settled Fine	62	M 2
9.0	OBR	Obstacle Rocks	76	M 4
9.0	MGO	General Observation	87	NA



Code: MGO
Description: General Observation

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0
Clock Start/From:
Clock To:
1st Value:
2nd Value:
Value Percent:
Step: NO

Remarks: ACCESS MH



Code: MGP

Description: General Photo

Distance (ft): 2.0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: Underside of frame



Code: SAV

Description: Surface Aggregate Visible

Distance (ft): 2.0
Structural Grade: 3
O&M Grade: 0
Clock Start/From: 12
Clock To: 12
1st Value:
2nd Value:

Step: NO

Remarks:

Value Percent:



Code: **DSF**

Description: Deposits Settled Fine

Distance (ft): 7.4
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 2
Clock To: 12
1st Value:

2nd Value:

Value Percent: 10.000 Step: NO

Remarks:

Wednesday, May 3, 2023



Code: OBR

Description: Obstacle Rocks

Distance (ft): 9.0
Structural Grade: 0
O&M Grade: 4
Clock Start/From: 4
Clock To: 8

1st Value: 2nd Value:

Value Percent: 30.000
Step: NO

Remarks:



Code: MGO

Description: General Observation

Distance (ft): 9.0
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: end survey