Manhole Inspection Report



Date: 04/24/2018 Weather: Coding: RZMACP

MH#: M-706-027 Owner: NA Len. Surveyed: 7.1 P.O.#: Surveyor: John Kuglmaier Rim to Invert: 6.5 Customer: 8.7 U-1215-07002349 Wall Material: **Brick** Cert. #:

Street: Intersection of 10th St. and Hwy 51. Project: Hobart, IN

City: Hobart, IN GPS Northing: 0.0 Location: GPS Easting: 0.0

Drain Area: Southeast GPS Accuracy: Nearest Meter

Cover Shape: Circular Evidence of Surcharge: No
Cover Size: Potential for Runoff: None

Comments:

O&M Index:	2.00	O&M Quick:	2100	O&M Rating:	2.00
Structural Index:	0.00	Structural Quick:	0000	Structural Rating:	0.00
Overall Index:	2.00	Overall Quick:	2100	Overall Rating:	2.00

Wednesday, May 3, 2023

Position	Code	Observation	Video (sec)	Grade
1-706-027				
.0	MGP	General Photo	10	NA
3.0	MGP	General Photo	30	NA
4.9	DAZ	Deposits Attached Other	47	M 2
6.2	MGO	General Observation	61	NA
Camera Direction				



Description:	General Photo
Distance (ft):	.0
Structural Grade: O&M Grade:	0
Clock Start/From: Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	

MGP

Wednesday, May 3, 2023 2

Code:



Code: MGP

Description: General Photo

Distance (ft): 3.0
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:

Step: NO

Remarks:



Code: DAZ

Description: Deposits Attached Other

Distance (ft): 4.9
Structural Grade: 0

O&M Grade: 2

Clock Start/From: 12

Clock To: 12

1st Value:

2nd Value:

Value Percent: 10.000
Step: NO

Remarks: Mixed materials



Code: MGO

Description: General Observation

Distance (ft): 6.2
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: Ins. Comp.

Wednesday, May 3, 2023 3