Manhole Ins	spection Repor	t			RedZon
Date:	04/23/2018	Weather:		Coding:	RZMACP
MH#:	M-706-050	Owner:	NA	Len. Surveyed	: 2.3
P.O.#:		Surveyor:	John Kuglmaier	Rim to Invert:	2.7
Customer:	8.7	Cert. #:	U-1215-07002349	Wall Material:	Concrete (reinforced)
Street:	450' South of 8th S	t. 344' West of W	Project:	Hobart, IN	
City:	Hobart, IN		GPS Northing:	0.0	
Location:			GPS Easting:	0.0	
Drain Area:	Southeast		GPS Accuracy:	Nearest Meter	
Cover Shape:	Circular		Evidence of Surcharge:	No	
Cover Size: Comments:	22.5		Potential for Runoff:	None	
O&M Index:	0.00	O&M Quick:	0000	O&M Rating:	0.00
Structural Index:	0.00	Structural Qu	ick: 0000	Structural Rating:	0.00
Overall Index:	0.00	Overall Quick	c: 0000	Overall Rating:	0.00

	Position	Code	Observation	Video (sec)	Grade		
M-706-050							
	.0	MGP	General Photo	10	NA		
- 11	1.9	MGO	General Observation	26	NA		
- 11							
- 11							
- 11							
- 11							
- 11							
- 11							
-							
ectio							
Camera Direction							
Jer.							
Ē							
+							
- 11							
- 11							



Code:	MGP
Description:	General Photo
	-
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	



Code:MGODescription:General Observation

Distance (ft):	1.9			
Structural Grade:	0			
O&M Grade:	0			
Clock Start/From:				
Clock To:				
1st Value:				
2nd Value:				
Value Percent:				
Step:	NO			
Remarks:	Ins. Comp.			