Manhole Ins	spection Report	t			RedZor
Date:	04/23/2018	Weather:		Coding:	RZMACP
MH#:	M-706-055	Owner:	NA	Len. Surveyed	: 4.6
P.O.#:		Surveyor:	John Kuglmaier	Rim to Invert:	4.7
Customer:	8.7	Cert. #:	U-1215-07002349	Wall Material:	Concrete (reinforced)
Street:	602' North of 10th	St. 446' West of	Project:	Hobart, IN	
City:	Hobart, IN		GPS Northing:	0.0	
Location:			GPS Easting:	0.0	
Drain Area:	Southeast		GPS Accuracy:	Nearest Meter	
Cover Shape:	Circular		Evidence of Surcharge:	Yes	
Cover Size: Comments:	22.5		Potential for Runoff:	None	
O&M Index:	2.00	O&M Quick:	2100	O&M Rating:	2.00
Structural Index:	0.00	Structural Qu	uick: 0000	Structural Rating:	0.00
Overall Index:	2.00	Overall Quic	k: 2100	Overall Rating:	2.00

Position	Code	Observation	Video (sec)	Grade
-706-055				
.0	MGP	General Photo	10	NA
.5	IS	Infil Stain	23	NA
2.3	MGP	General Photo	40	NA
2.6	DAZ	Deposits Attached Other	55	M 2
3.9	MGO	General Observation	69	NA



Code:	MGP
Description:	<b>General Photo</b>
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	



Code:	IS
Description:	Infil Stain
	_
Distance (ft):	.5
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	12
Clock To:	12
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	



Code: Description:	MGP General Photo
Distance (ft): Structural Grade: O&M Grade: Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Step:	2.3 0 0
Remarks:	



Code:	DAZ
Description:	Deposits Attached Other
	• •
Distance (ft):	2.6
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	12
Clock To:	12
1st Value:	
2nd Value:	
Value Percent:	10.000
Step:	NO
Remarks:	Mixed materials



Code:MGODescription:General Observation

Distance (ft):	3.9
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	Ins. Comp.