Manhole Inspection Report



Date: 04/23/2018 Weather: Coding: RZMACP

MH#: M-706-057 Owner: NA Len. Surveyed: 6.3
P.O.#: Surveyor: John Kuglmaier Rim to Invert: 6.3

Customer: 8.7 Cert. #: U-1215-07002349 Wall Material: Concrete

(reinforced)

Street: 520' North of 10th St. 279' East of La Project: Hobart, IN

City: Hobart, IN GPS Northing: 0.0 Location: GPS Easting: 0.0

Drain Area: Southeast GPS Accuracy: Nearest Meter

Cover Shape: Circular Evidence of Surcharge: No
Cover Size: Potential for Runoff: None

Comments:

O&M Index:	2.00	O&M Quick:	2100	O&M Rating:	2.00
Structural Index:	0.00	Structural Quick:	0000	Structural Rating:	0.00
Overall Index:	2.00	Overall Quick:	2100	Overall Rating:	2.00

Wednesday, May 3, 2023

	Position	Code	Observation	Video (sec)	Grade
M-706-05	57				
	0	MGP	General Photo	10	NA
- 11	2.3	MGP	General Photo	28	NA
- 11	3.7	DSF	Deposits Settled Fine	45	M 2
- 11	5.5	MGO	General Observation	60	NA
ш	//				
Ш					
Camera Direction					
Dire					
nera					
Ca					
Ш					

Code:



Description:	General Photo		
Distance (ft):	.0		
Structural Grade:	0		
O&M Grade:	0		
Clock Start/From:			
Clock To:			
1st Value:			
2nd Value:			
Value Percent:			
Step:	NO		
Remarks:			

MGP

Wednesday, May 3, 2023



Code: MGP


Description: General Photo

Distance (ft): 2.3
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks:



Code: **DSF**

Description: Deposits Settled Fine

Distance (ft): 3.7
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 12
Clock To: 12
1st Value:

2nd Value:
Value Percent: 10.000
Step: NO

Remarks:

Code:

Description: General Observation

MGO



Distance (ft): 5.5
Structural Grade: 0

O&M Grade: **0**

Clock Start/From: Clock To:

1st Value: 2nd Value:

Value Percent: Step: **NO**

Remarks: Ins. Comp.

Wednesday, May 3, 2023