## **Manhole Inspection Report**



Date: 04/23/2018 Weather: Coding: RZMACP

MH#: M-706-060 Owner: NA Len. Surveyed: 5.4
P.O.#: Surveyor: John Kuglmaier Rim to Invert: 5.6

Customer: 8.7 Cert. #: U-1215-07002349 Wall Material: Concrete

(reinforced)

Street: 465' North of 10th St. 177' East of La Project: Hobart, IN

City: Hobart, IN GPS Northing: 0.0 Location: GPS Easting: 0.0

Drain Area: Southeast GPS Accuracy: Nearest Meter

Cover Shape: Circular Evidence of Surcharge: No
Cover Size: 26.0 Potential for Runoff: None

Comments:

O&M Index:	0.00	O&M Quick:	0000	O&M Rating:	0.00
Structural Index:	0.00	Structural Quick:	0000	Structural Rating:	0.00
Overall Index:	0.00	Overall Quick:	0000	Overall Rating:	0.00


Wednesday, May 3, 2023

Position	Code	Observation	Video (sec)	Grade
л-706-060				
.0	MGP	General Photo	10	NA
2.0	MGP	General Photo	28	NA
4.5	MGO	General Observation	47	NA
Camera Direction				



Code:	MGP
Description:	<b>General Photo</b>
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	

Wednesday, May 3, 2023



Code: MGP

Description: General Photo

Distance (ft): 2.0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks:



Code: MGO

Description: General Observation

Distance (ft): 4.5
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: Ins. Comp.