Date:	04/18/2018	Weather:			Coding:	RZMACP
MH#:	M-707-021	Owner:	NA		Len. Surveyed:	5.0
P.O.#:		Surveyor:	John Ku	glmaier	Rim to Invert:	5.5
Customer:		Cert. #:	U-1215-	07002349	Wall Material:	Concrete (reinforced)
Street:	Lincoln St. 282' South of 13th St. Project:		Hobart, IN			
City:	Hobart, IN		GPS North	ning:	2906561.532	
Location:			GPS Eastin	ng:	2906561.532	
Drain Area:	Southeast		GPS Accu	асу:	Sub-Meter	
Cover Shape:	Circular		Evidence	of Surcharge:	No	
Cover Size: Comments:	22.5		Potential	for Runoff:	None	
O&M Index:	3.00	O&M Quick:		3100	O&M Rating:	3.00
Structural Index:	5.00	Structural Qu	ick:	5100	Structural Rating:	5.00
Overall Index:	4.00	Overall Quic	k:	5131	Overall Rating:	8.00

Position	Code	Observation	Video (sec)	Grade
-707-021				
.0	MGP	General Photo	10	NA
2.1	MGP	General Photo	28	NA
2.4	DSF	Deposits Settled Fine	42	M 3
3.9	HSV	Hole Soil Visible	57	S 5
4.3	MGO	General Observation	70	NA



Code:	MGP
Description:	General Photo
	_
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	

\_\_\_\_



Code:	MGP
Description:	<b>General Photo</b>
Distance (ft):	2.1
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	



Code: Description:	DSF Deposits Settled Fine
Distance (ft): Structural Grade: O&M Grade: Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Step:	2.4 0 3 12 12 15.000 NO
Remarks:	



Code:	HSV
Description:	Hole Soil Visible
Distance (ft):	3.9
Structural Grade:	5
O&M Grade:	0
Clock Start/From:	12
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	



Code:MGODescription:General Observation

4.3
0
0
NO
Ins. Comp.