Date:	04/18/2018	Weather:		Coding:	RZMACP
MH#:	M-707-022	Owner:	NA	Len. Surveyed:	5.0
P.O.#:		Surveyor:	John Kuglmaier	Rim to Invert:	5.7
Customer:		Cert. #:	U-1215-07002349	Wall Material:	Concrete (reinforced)
Street:	Intersection of 13th St. and Lincoln S Project: Hobart, IN				
City:	Hobart, IN	(GPS Northing:	2906555.757	
Location:		(GPS Easting:	2906555.757	
Drain Area:	Southeast	(GPS Accuracy:	Sub-Meter	
Cover Shape:	Circular	E	Evidence of Surcharge:	No	
Cover Size: Comments:	22.5	Potential for Runoff:		None	
O&M Index:	2.00	O&M Quick:	2100	O&M Rating:	2.00
Structural Index:	0.00	Structural Quid	ck: 0000	Structural Rating:	0.00
Overall Index:	2.00	Overall Quick:	2100	Overall Rating:	2.00

Position	Code	Observation	Video (sec)	Grade
1-707-022				
.0	MGP	General Photo	10	NA
2.1	MGP	General Photo	28	NA
2.4	DSF	Deposits Settled Fine	42	M 2
4.3	MGO	General Observation	58	NA



Code:	MGP
Description:	General Photo
	_
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	



Code: MGP Description: **General Photo** Distance (ft): 2.1 Structural Grade: 0 O&M Grade: 0 Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Step: NO

Remarks:



	ie
Distance (ft):2.4Structural Grade:0O&M Grade:2Clock Start/From:12Clock To:121st Value:2Yalue Percent:10.000Step:NORemarks:10.000	



Code:	MGO
Description:	General Observation
Distance (ft):	4.3
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	Ins. Comp.