Manhole Inspection Report



Date: 04/18/2018 Weather: Coding: RZMACP

MH#: M-707-030 Owner: NA Len. Surveyed: 5.9
P.O.#: Surveyor: John Kuglmaier Rim to Invert: 6.6

Customer: Cert. #: U-1215-07002349 Wall Material: Concrete

(reinforced)

Street: Lincoln St. 229' South of 11th St. Project: Hobart, IN

City: Hobart, IN GPS Northing: 2906541.251

Location: GPS Easting: 2906541.251
Drain Area: Southeast GPS Accuracy: Sub-Meter

Cover Shape: Circular Evidence of Surcharge: No
Cover Size: Potential for Runoff: None

Comments:

2.00 2100 2.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Index: Structural Quick: Structural Rating: 2.00 2100 2.00 Overall Index: Overall Quick: Overall Rating:

Wednesday, May 3, 2023

Position	Code	Observation	Video (sec)	Grade
M-707-030				
.0	MGP	General Photo	10	NA
2.5	MGP	General Photo	29	NA
3.7	DSF	Deposits Settled Fine	45	M 2
5.2	MGO	General Observation	59	NA
Camera Direction				



Description:	General Photo		
	_		
Distance (ft):	.0		
Structural Grade:	0		
O&M Grade:	0		
Clock Start/From:			
Clock To:			
1st Value:			
2nd Value:			
Value Percent:			
Step:	NO		
Remarks:			

MGP

Wednesday, May 3, 2023

Code:



Code: **MGP**

Description: **General Photo**

Distance (ft): 2.5 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks:



Code: **DSF**

Description: **Deposits Settled Fine**

Distance (ft): 3.7 Structural Grade: 0 O&M Grade: 2 Clock Start/From: 12 Clock To: 12 1st Value:

2nd Value:

Value Percent: 10.000 NO Step:

Remarks:



Code: MGO

General Observation Description:

Distance (ft): 5.2 Structural Grade: 0 O&M Grade: 0 Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: Ins. Comp.

Wednesday, May 3, 2023 3