## **Manhole Inspection Report**



Date: **04/17/2018** Weather:

MH#: M-707-036 Owner: NA Len. Surveyed: 6.3
P.O.#: Surveyor: John Kuglmaier Rim to Invert: 6.6

Customer: Cert. #: U-1215-07002349 Wall Material: Concrete

(reinforced)

**RZMACP** 

Coding:

Street: Intersection of State St. and 13th St. Project: Hobart, IN

City: Hobart, IN GPS Northing: 2906220.875

Location: GPS Easting: 2906220.875

Drain Area: Southeast GPS Accuracy: Sub-Meter Cover Shape: Evidence of Surcharge: No

Cover Size: 22.5 Potential for Runoff: None

Comments:

2.00 2100 2.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Index: Structural Quick: Structural Rating: 2.00 2100 2.00 Overall Index: Overall Quick: Overall Rating:

Wednesday, May 3, 2023

Po	osition C	Code	Observation	Video (sec)	Grade
M-707-036					
.0	N	ИGР	General Photo	10	NA
2.4	1 N	ИGP	General Photo	28	NA
3.2	2 D	DAZ	Deposits Attached Other	44	M 2
5.4	1 N	ИGO	General Observation	59	NA
Camera Direction					

Code:



Description:	General Photo
Distance (ft): Structural Grade:	.0 0
O&M Grade:	0
Clock Start/From: Clock To:	
1st Value: 2nd Value:	
Value Percent: Step:	NO
Remarks:	

MGP

Wednesday, May 3, 2023



Code: MGP

Description: General Photo

Distance (ft): 2.4
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks:



Code: DAZ

Description: Deposits Attached Other

Distance (ft): 3.2
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 12
Clock To: 12
1st Value:

2nd Value:

Value Percent: 5.000 Step: NO

Remarks: Mixed materials



Code: MGO

Description: General Observation

Distance (ft): 5.4
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: Ins. Comp.

Wednesday, May 3, 2023