Manhole Inspection Report



Date: 04/16/2018 Weather: Coding: RZMACP

 MH#:
 M-707-045
 Owner:
 NA
 Len. Surveyed:
 6.1

 P.O.#:
 Surveyor:
 John Kuglmaier
 Rim to Invert:
 6.5

Customer: Cert. #: U-1215-07002349 Wall Material: Concrete

(reinforced)

Street: 13th Pl. 600' East of Flemming St. Project: Hobart, IN

City: Hobart, IN GPS Northing: 2905942.506

Location: GPS Easting: 2905942.506

Drain Area: Southwest GPS Accuracy: Sub-Meter

Cover Shape: Circular Evidence of Surcharge: No
Cover Size: 29.0 Potential for Runoff: None

Comments:

O&M Index:	2.00	O&M Quick:	2100	O&M Rating:	2.00
Structural Index:	0.00	Structural Quick:	0000	Structural Rating:	0.00
Overall Index:	2.00	Overall Quick:	2100	Overall Rating:	2.00

Wednesday, May 3, 2023

	Position	Code	Observation	Video (sec)	Grade
M-707-04	15				
	0	MGP	General Photo	10	NA
- 11	2.0	MGP	General Photo	28	NA
- 11	3.4	DSF	Deposits Settled Fine	44	M 2
- 11	5.4	MGO	General Observation	60	NA
Camera Direction					

Code:



Description:	General Photo	
Distance (ft):	.0	
Structural Grade:	0	
O&M Grade:	0	
Clock Start/From:		
Clock To:		
1st Value:		
2nd Value:		
Value Percent:		
Step:	NO	
Remarks:		

MGP

Wednesday, May 3, 2023



Code: MGP

Description: General Photo

Distance (ft): 2.0
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks:



Code: **DSF**

Description: Deposits Settled Fine

Distance (ft): 3.4
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 12
Clock To: 12
1st Value:

2nd Value:
Value Percent: 5.000
Step: NO

Remarks:

Code:

MGO

Description: General Observation



Distance (ft): 5.4

Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:

Step: NO
Remarks: Ins. Comp.

Wednesday, May 3, 2023