## **Manhole Inspection Report**



Date: 04/17/2018 Weather: Coding: RZMACP

MH#: M-707-058 Owner: NA Len. Surveyed: 9.3
P.O.#: Surveyor: John Kuglmaier Rim to Invert: 9.4

Customer: Cert. #: U-1215-07002349 Wall Material: Concrete

(reinforced)

Street: 12th St. 615' West of State St. Project: Hobart, IN

City: Hobart, IN GPS Northing: 2905601.457

Location: GPS Easting: 2905601.457

Drain Area: Southwest GPS Accuracy: Sub-Meter

Cover Shape: Circular Evidence of Surcharge: No
Cover Size: Potential for Runoff: None

Comments:

2.00 2100 2.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Index: Structural Quick: Structural Rating: 2.00 2100 2.00 Overall Index: Overall Quick: Overall Rating:

Wednesday, May 3, 2023

Position	Code	Observation	Video (sec)	Grade
I- <b>7</b> 07- <b>0</b> 58				
.0	MGP	General Photo	10	NA
2.7	MGP	General Photo	29	NA
6.0	DSF	Deposits Settled Fine	50	M 2
8.0	MGO	General Observation	65	NA
111				



Description: **General Photo** Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Step: NO Remarks:

MGP

Wednesday, May 3, 2023 2

Code:



Code: MGP


Description: General Photo

Distance (ft): 2.7
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks:



Code: **DSF** 

Description: Deposits Settled Fine

Distance (ft): 6.0
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 12
Clock To: 12
1st Value:

2nd Value:
Value Percent: 5.000
Step: NO

Remarks:

Code: MGO

Description: General Observation



Distance (ft): 8.0 Structural Grade: 0

O&M Grade: **0** 

Clock Start/From: Clock To:

1st Value: 2nd Value:

Value Percent: Step: **NO** 

Remarks: Ins. Comp.

Wednesday, May 3, 2023 3