## **Manhole Inspection Report**



Date: **04/17/2018** 

M-707-060

Weather:

Coding:

RZMACP

9.9

10.0

MH#:

Owner: NA

Len. Surveyed: Rim to Invert:

P.O.#:

Surveyor: Cert. #: John Kuglmaier U-1215-07002349

Wall Material:

Concrete (reinforced)

Street: City:

Customer:

12th St. 326' East of Lake Park Ave.

Project: GPS Northing: Hobart, IN 2904967.664

Location:

Hobart, IN

CDS Facting

2904967.664

Drain Area:

GPS Easting:

2904967.664 Sub-Meter

Cover Shape:

Southwest Circular GPS Accuracy:

Evidence of Surcharge: **No** 

Cover Size:

22.5

Potential for Runoff: None

Comments:

O&M Index: Structural Index:

Overall Index:

2.00 O

2.00


\_O&M Quick: \_Structural Quick: Overall Quick: 2100 ( 0000 <u>s</u> 2100 (

\_O&M Rating:
\_Structural Rating:
Overall Rating:

2.00 0.00 2.00

Po	osition C	Code	Observation	Video (sec)	Grade
M-707-960					
.0	N	ИGP	General Photo	10	NA
2.5	5 N	ЛGP	General Photo	29	NA
7.2	2 D	SF	Deposits Settled Fine	52	M 2
9.0	0 N	ИGO	General Observation	67	NA
Camera Direction					

Code:



**General Photo** Description: Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Step: NO Remarks:

MGP

Wednesday, May 3, 2023 2



Code: MGP


Description: General Photo

Distance (ft): 2.5
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks:



Code: **DSF** 

Description: Deposits Settled Fine

Distance (ft): 7.2
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 12
Clock To: 12
1st Value:

Value Percent: 5.000 Step: NO

Remarks:

2nd Value:

Code: MGO

Description: General Observation



Distance (ft): 9.0

Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: Ins. Comp.

Wednesday, May 3, 2023