Manhole Inspection Report



Date: 04/24/2018 Weather: Coding: RZMACP

MH#: M-707-074 Owner: NA Len. Surveyed: 8.5 P.O.#: Surveyor: John Kuglmaier Rim to Invert: 8.9 Customer: 8.7 Cert. #: U-1215-07002349 Wall Material: **Brick**

Street: Intersection of State St. and 10th St. Project: Hobart, IN

City: Hobart, IN GPS Northing: 0.0

Location: GPS Easting: **0.0**

Drain Area: Southeast GPS Accuracy: Nearest Meter

Cover Shape: Circular Evidence of Surcharge: No
Cover Size: Potential for Runoff: None

Comments:

O&M Index:	3.00	O&M Quick:	3100	O&M Rating:	3.00
Structural Index:	0.00	Structural Quick:	0000	Structural Rating:	0.00
Overall Index:	3.00	Overall Quick:	3100	Overall Rating:	3.00

Wednesday, May 3, 2023

	Position	Code	Observation	Video (sec)	Grade
M-707-0	74				
	V. O	MGP	General Photo	10	NA
- 11	1.0	IS	Infil Stain	24	NA
	2.8	MGP	General Photo	41	NA
- 11	6.4	DAZ	Deposits Attached Other	62	M 3
- 11	7.6	MGO	General Observation	76	NA
Camera Direction					



Description:	General Photo
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	

MGP

Wednesday, May 3, 2023

Code:



Code: IS

Description: Infil Stain

Distance (ft): 1.0
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 1

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks:



Code: MGP

Description: General Photo

Distance (ft): 2.8
Structural Grade: 0
O&M Grade: 0
Clock Start/From:
Clock To:

1st Value: 2nd Value: Value Percent:

Step: NO

Remarks:

Code: DAZ

Description: Deposits Attached Other



Distance (ft): 6.4
Structural Grade: 0

O&M Grade: 3

Clock Start/From: 12

Clock To: 12

1st Value: 2nd Value:

Value Percent: 15.000 Step: NO

Remarks: Mixed materials

Wednesday, May 3, 2023 3



Code: MGO

Description: General Observation

Distance (ft): 7.6
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: Ins. Comp.

4

Wednesday, May 3, 2023