

# Manhole Inspection Report



|           |                   |           |                     |                |                              |
|-----------|-------------------|-----------|---------------------|----------------|------------------------------|
| Date:     | <b>04/24/2018</b> | Weather:  |                     | Coding:        | <b>RZMACP</b>                |
| MH#:      | <b>M-707-075</b>  | Owner:    | <b>NA</b>           | Len. Surveyed: | <b>8.0</b>                   |
| P.O.#:    |                   | Surveyor: | <b>Jen Costello</b> | Rim to Invert: | <b>7.8</b>                   |
| Customer: | <b>8.7</b>        | Cert. #:  | <b>U-907-5518</b>   | Wall Material: | <b>Concrete (reinforced)</b> |

|              |   |                        |                      |
|--------------|---|------------------------|----------------------|
| Street:      | <b>On State St. 50' South of 10th St.</b> | Project:               | <b>Hobart, IN</b>    |
| City:        | <b>Hobart, IN</b>                         | GPS Northing:          | <b>0.0</b>           |
| Location:    |   | GPS Easting:           | <b>0.0</b>           |
| Drain Area:  | <b>Southeast</b>                          | GPS Accuracy:          | <b>Nearest Meter</b> |
| Cover Shape: | <b>Circular</b>                           | Evidence of Surcharge: | <b>No</b>            |
| Cover Size:  | <b>22.5</b>                               | Potential for Runoff:  | <b>None</b>          |
| Comments:    |   |                        |                      |

|                   |             |                   |             |                    |             |
|-------------------|-------------|-------------------|-------------|--------------------|-------------|
| O&M Index:        | <u>2.00</u> | O&M Quick:        | <u>2100</u> | O&M Rating:        | <u>2.00</u> |
| Structural Index: | <u>0.00</u> | Structural Quick: | <u>0000</u> | Structural Rating: | <u>0.00</u> |
| Overall Index:    | <u>2.00</u> | Overall Quick:    | <u>2100</u> | Overall Rating:    | <u>2.00</u> |

| Position         | Code | Observation           | Video (sec) | Grade |
|------------------|------|-----------------------|-------------|-------|
| <b>M-707-075</b> |      |                       |             |       |
| .0               | MGO  | General Observation   | 10          | NA    |
| 2.0              | MGP  | General Photo         | 27          | NA    |
| 4.4              | IS   | Infil Stain           | 45          | NA    |
| 6.9              | DSF  | Deposits Settled Fine | 61          | M 2   |
| 8.0              | MGO  | General Observation   | 73          | NA    |

Code: **MGO**  
Description: **General Observation**



Distance (ft): **.0**  
Structural Grade: **0**  
O&M Grade: **0**  
Clock Start/From:  
Clock To:  
1st Value:  
2nd Value:  
Value Percent:  
Step: **NO**  
Remarks: **ACCESS MH**



Code: **MGP**  
Description: **General Photo**

Distance (ft): **2.0**  
Structural Grade: **0**  
O&M Grade: **0**  
Clock Start/From:  
Clock To:  
1st Value:  
2nd Value:  
Value Percent:  
Step: **NO**  
Remarks: **Underside of frame**

---



Code: **IS**  
Description: **Infil Stain**


Distance (ft): **4.4**  
Structural Grade: **0**  
O&M Grade: **0**  
Clock Start/From: **12**  
Clock To: **12**  
1st Value:  
2nd Value:  
Value Percent:  
Step: **NO**  
Remarks:

---



Code: **DSF**  
Description: **Deposits Settled Fine**

Distance (ft): **6.9**  
Structural Grade: **0**  
O&M Grade: **2**  
Clock Start/From: **12**  
Clock To: **6**  
1st Value:  
2nd Value:  
Value Percent: **5.000**  
Step: **NO**  
Remarks:



Code: **MGO**  
Description: **General Observation**

Distance (ft): **8.0**  
Structural Grade: **0**  
O&M Grade: **0**  
Clock Start/From:  
Clock To:  
1st Value:  
2nd Value:  
Value Percent:

Step: **NO**  
Remarks: **end survey**