Manhole Inspection Report

Date:	04/16/2018	Weather:		Coding:	RZMACP
MH#:	M-707-078	Owner:	NA	Len. Surveyed:	5.5
P.O.#:		Surveyor:	Jen Costello	Rim to Invert:	5.9
Customer:		Cert. #:	U-907-5518	Wall Material:	Brick
Street:	On 13th St. 282' W	est of State St.	Project:	Hobart, IN	
City:	Hobart, IN		GPS Northing:	2905938.807	
Location:			GPS Easting:	2905938.807	
Drain Area:	Southeast		GPS Accuracy:	Sub-Meter	
Cover Shape:	Circular		Evidence of Surcharge:	Νο	
Cover Size:	29.0		Potential for Runoff:	None	
Comments:	RING CAME UP WIT	TH THE LID			
O&M Index:	0.00	O&M Quick:	0000	O&M Rating:	0.00
Structural Index:	3.00	Structural Qui	ck: 3200	Structural Rating:	6.00
Overall Index:	3.00	Overall Quick	. 3200	Overall Rating:	6.00

RedZone


	osition	Code	Observation	Video (sec)	Grade
M-707-078					
0.	1	MGO	General Observation	10	NA
.0	[DB	Displaced Brick	20	S 3
1.	7 1	MGO	General Observation	37	NA
$\int 1.$	7 9	SAV	Surface Aggregate Visible	50	S 3
5.	5 I	MGO	General Observation	69	NA
Camera Direction					



Code: Description:	MGO General Observation
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	ACCESS MH



Code:	DB
Description:	Displaced Brick
Distance (ft):	•
Distance (ft):	.0
Structural Grade:	3
O&M Grade:	0
Clock Start/From:	1
Clock To:	7
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	



Code: Description:	MGO General Observation
Distance (ft): Structural Grade: O&M Grade: Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Step:	1.7 0 0
Remarks:	UNDERSIDE OF FRAME



Code: Description:	SAV Surface Aggregate Visible
Distance (ft):	1.7
Structural Grade:	3
O&M Grade:	0
Clock Start/From:	12
Clock To:	12
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	



Code:MGODescription:General Observation

Distance (ft):	5.5
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	END SURVEY