

Date:	04/18/2018	Weather:		Coding:	RZMACP
MH#:	M-707-080	Owner:	NA	Len. Surveyed:	2.9
P.O.#:		Surveyor:	Jen Costello	Rim to Invert:	3.6
Customer:		Cert. #:	U-907-5518	Wall Material:	Concrete (reinforced)
Street:	Intersection of 13th St. and Lincoln S Project: Hobart, IN				
City:	Hobart, IN		GPS Northing:	2906558.664	
Location:			GPS Easting:	2906558.664	
Drain Area:	Southeast		GPS Accuracy:	Sub-Meter	
Cover Shape:	Circular		Evidence of Surcharge:	No	
Cover Size: Comments:	22.5		Potential for Runoff:	None	
O&M Index:	0.00	O&M Quick:	0000	O&M Rating:	0.00
Structural Index:	3.50	Structural Qu	iick: 5121	Structural Rating:	7.00
Overall Index:	3.50	Overall Quicl	c: 5121	Overall Rating:	7.00

	Position	Code	Observation	Video (sec)	Grade
M-707-08	0				
	.0	MGO	General Observation	10	NA
	\.0	SSS	Surface Spalling	20	S 2
	1.2	В	Broken	34	S 5
	1.2	MGP	General Photo	46	NA
	2.9	MGO	General Observation	63	NA
Camera Direction					



Code: Description:	MGO General Observation
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	access mh



Code:	SSS
Description:	Surface Spalling
Distance (ft):	.0
Structural Grade:	2
O&M Grade:	0
Clock Start/From: Clock To: 1st Value: 2nd Value:	12 12
Value Percent: Step: Remarks:	NO



Code: B Description: B	roken
Structural Grade:5O&M Grade:0Clock Start/From:1:Clock To:31st Value:22nd Value:Value Percent:Step:N	2 2 O round incoming line



MGP General Photo
1.2
0
0
NO
underside of frame



Code:MGODescription:General Observation

Distance (ft):	2.9
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	end survey