Date:	04/19/2018	Weather:		Coding:	RZMACP
MH#:	M-708-025	Owner:	NA	Len. Surveyed:	4.1
P.O.#:		Surveyor:	John Kuglmaier	Rim to Invert:	4.8
Customer:		Cert. #:	U-1215-07002349	Wall Material:	Concrete (reinforced)
Street:	299' Southwest of Lake St. and Coral Project: Hobart, IN				
City:	Hobart, IN	(GPS Northing:	2905307.2	
Location:		(GPS Easting:	2905307.2	
Drain Area:	Southwest	(GPS Accuracy:	Sub-Meter	
Cover Shape:	Circular	I	Evidence of Surcharge:	No	
Cover Size: Comments:	22.5	I	Potential for Runoff:	None	
O&M Index:	0.00	O&M Quick:	0000	O&M Rating:	0.00
Structural Index:	0.00	Structural Quid	ck: 0000	Structural Rating:	0.00
Overall Index:	0.00	Overall Quick:	0000	Overall Rating:	0.00

Position	Code	Observation	Video (sec)	Grade
M-708-025				
.0	MGP	General Photo	10	NA
1.0	IS	Infil Stain	24	NA
/1.0	IS	Infil Stain	35	NA
//2.1	MGP	General Photo	51	NA
3.6	MGO	General Observation	68	NA
Camera Direction				




Code:	MGP
Description:	General Photo
Distance (ft):	•
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	



Code:	IS
Description:	Infil Stain
Distance (ft):	1.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	9
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	



Code: Description:	IS Infil Stain
Distance (ft): Structural Grade: O&M Grade: Clock Start/From: Clock To:	1.0 0 0 3
1st Value: 2nd Value: Value Percent: Step: Remarks:	ΝΟ



Code:	MGP
Description:	General Photo
Distance (ft):	2.1
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	



Code:MGODescription:General Observation

Distance (ft):	3.6	
Structural Grade:	0	
O&M Grade:	0	
Clock Start/From:		
Clock To:		
1st Value:		
2nd Value:		
Value Percent:		
Step:	NO	
Remarks:	Ins. Comp.	