Manhole Inspection Report



Date:

04/19/2018

Weather:

NA

Coding:

RZMACP

MH#: P.O.#:

M-708-101

Owner:

John Kuglmaier

Len. Surveyed: 10.6 11.6 Rim to Invert:

Customer:

Surveyor: Cert. #:

U-1215-07002349

Wall Material:

Concrete (reinforced)

Street: City:

Bracken Parkway. Lake Park Ave.

Project: **GPS Northing:**

Hobart, IN 2904714.968

Location:

Hobart, IN

GPS Easting:

2904714.968

Drain Area:

Southwest

22.5

Sub-Meter

Cover Shape: Cover Size:

Circular

GPS Accuracy: Evidence of Surcharge:

No

Comments:

Potential for Runoff:

None

O&M Index:

2.00 O&M Quick: 0.00 Structural Quick:

2100 0000

O&M Rating: Structural Rating:

2.00 0.00 2.00

Structural Index: Overall Index:

2.00 Overall Quick:

2100 Overall Rating:

Wednesday, May 3, 2023 1

	Position	Code	Observation	Video (sec)	Grade
M-708-301					
	<u></u>	MGP	General Photo	10	NA
- 11	2.5	MGP	General Photo	29	NA
- 11	7.5	DSF	Deposits Settled Fine	52	M 2
- 11	9.0	MGO	General Observation	67	NA
- 11.	/				
111/					
- 11					
- 11					
- 11					
Camera Direction					
irec					
5 D					
e l					
ž					
- 1111					
- 111					
+					
- 111					
- 11					
- 11					
- 11					
	_				

Code:



Description: **General Photo** Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Step: NO Remarks:

MGP

Wednesday, May 3, 2023 2



Code: MGP

Description: General Photo

Distance (ft): 2.5
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks:



Code: **DSF**

Description: Deposits Settled Fine

Distance (ft): 7.5
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 12
Clock To: 6
1st Value:

Value Percent: 5.000 Step: NO

Remarks:

2nd Value:



Code: MGO

Description: General Observation

Distance (ft): 9.0
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: Ins. Comp.

Wednesday, May 3, 2023