## **Manhole Inspection Report**



Date: 04/10/2018 Weather: Coding: RZMACP

MH#: M-708-110 Owner: NA Len. Surveyed: 8.3
P.O.#: Surveyor: John Kuglmaier Rim to Invert: 9.0

Customer: Cert. #: U-1215-07002349 Wall Material: Concrete

(reinforced)

Street: Bracken Parkway. 104' West of Linc Project: Hobart, IN

City: Hobart, IN GPS Northing: 2906438.065

Location: GPS Easting: 2906438.065
Drain Area: Southwest GPS Accuracy: Sub-Meter

Cover Shape: Circular Evidence of Surcharge: No

Cover Size: 22.5 Potential for Runoff: None

Comments:

1.50 2111 3.00 O&M Index: O&M Quick: O&M Rating: 0000 0.00 0.00 Structural Index: Structural Quick: Structural Rating: 1.50 2111 3.00 Overall Index: Overall Quick: Overall Rating:

Wednesday, May 3, 2023

	Position	Code	Observation	Video (sec)	Grade
M-708-1	10				
	0	MGP	General Photo	10	NA
- 11	2.2	MGP	General Photo	28	NA
- 11	5.5	DSF	Deposits Settled Fine	49	M 2
- 11	5.5	VC	Vermin Cockroach	60	M 1
- 11	6.9	MGO	General Observation	75	NA
Camera Direction					



Description:	General Photo
Distance (ft): Structural Grade: O&M Grade: Clock Start/From:	.0 0 0
Clock To: 1st Value: 2nd Value: Value Percent:	
Step: Remarks:	NO

MGP

Wednesday, May 3, 2023

Code:



Code: MGP

Description: General Photo

Distance (ft): 2.2
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks:



Code: **DSF** 

Description: Deposits Settled Fine

Distance (ft): 5.5
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 6
Clock To: 12
1st Value:

2nd Value:

Value Percent: 5.000 Step: NO

Remarks:

Code:

VC

Description: Vermin Cockroach



Distance (ft): 5.5

Structural Grade: 0

O&M Grade: 1

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks:

Wednesday, May 3, 2023



Code: MGO

Description: General Observation

Distance (ft): 6.9
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: Ins. Comp.

4

Wednesday, May 3, 2023