## **Manhole Inspection Report**



Date: 09/21/2022 Weather: Coding: RZMACP

MH#: M-708-122 Owner: NA Len. Surveyed: 6.5

P.O.#: Surveyor: Jen Costello Rim to Invert: 7.7

Customer: Cert. #: U-907-5518 Wall Material: Other

Street: Tamarack Dr. 248' East of Redbud Dr. Project: Hobart, IN
City: Hobart, IN GPS Northing: 2280868.332

Location:Main Highway - Suburban/RuralGPS Easting:2905427.377Drain Area:SouthwestGPS Accuracy:Sub-Meter

Cover Shape: Circular Evidence of Surcharge: Cover Size: 24.0 Potential for Runoff:

Comments:

O&M Index:	2.00	O&M Quick:	2100	O&M Rating:	2.00
Structural Index:	1.00	Structural Quick:	1600	Structural Rating:	6.00
Overall Index:	1.14	Overall Quick:	2116	Overall Rating:	8.00

	Code	Observation	Video (sec)	Grade
08-122				
.0	MGO	General Observation	10	NA
0.	SRI	Surface Roughness Increased	21	S 1
2.2	MGO	General Observation	39	NA
6.5	DSF	Deposits Settled Fine	62	M 2
6.5	SRI	Surface Roughness Increased	73	S 1
6.5	MGO	General Observation	84	NA

Code:



Description:	General Observation	
Distance (ft):	.0	
Structural Grade:	0	
O&M Grade:	0	
Clock Start/From:		
Clock To:		
1st Value:		
2nd Value:		
Value Percent:		
Step:	NO	
Remarks:	access mh	

MGO



Code: SRI

Description: Surface Roughness Increased

Distance (ft): .0
Structural Grade: 1
O&M Grade: 0
Clock Start/From: 12
Clock To: 12
1st Value:

2nd Value: Value Percent:

Step: NO

Remarks:



Code: MGO

Description: General Observation

Distance (ft): 2.2
Structural Grade: 0
O&M Grade: 0
Clock Start/From:
Clock To:

1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: underside of frame



Code: **DSF** 

Description: Deposits Settled Fine

Distance (ft): 6.5
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 12
Clock To: 12
1st Value:

2nd Value:

Value Percent: 5.000 Step: NO

Remarks:



Code: SRI

Description: **Surface Roughness Increased** 

Distance (ft): 6.5 Structural Grade: 1 O&M Grade: 0 Clock Start/From: 12 Clock To: 12

1st Value: 2nd Value: Value Percent:

Step: NO

Remarks:



Code: MGO

Description: **General Observation** 

Distance (ft): 6.5 Structural Grade: 0 0 O&M Grade:

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

NO Step:

Remarks: end of survey