Manhole Inspection Report



Date: 11/07/2022 Weather: Coding: RZMACP

MH#: M-708-132 Owner: NA Len. Surveyed: 5.4
P.O.#: Surveyor: Jen Costello Rim to Invert: 6.1

Customer: Cert. #: U-907-5518 Wall Material: Concrete (non-

reinforced)

Street: Intersection of Heather Ln. and Mag Project: Missing GPS

City: Hobart, IN GPS Northing: 2280705.251
Location: GPS Easting: 2905825.997

Drain Area: Southwest GPS Accuracy: Sub-Meter

Cover Shape: Circular Evidence of Surcharge: No
Cover Size: 24.0 Potential for Runoff: None

Comments:

2.00 2100 2.00 O&M Index: O&M Quick: O&M Rating: 1.29 3116 9.00 Structural Index: Structural Quick: Structural Rating: 1.38 3121 11.00 Overall Index: Overall Quick: Overall Rating:

Wednesday, May 3, 2023

Position	Code	Observation	Video (sec)	Grade
)8- 1 32				
.0	MGO	General Observation	10	NA
0.	SRI	Surface Roughness Increased	22	S 1
2.1	MGO	General Observation	39	NA
4.8	DSF	Deposits Settled Fine	58	M 2
4.8	SRI	Surface Roughness Increased	69	S 1
4.8	SRI	Surface Roughness Increased	81	S 1
4.8	SAV	Surface Aggregate Visible	92	S 3



Description:

General Observation

Distance (ft):

Structural Grade:

O&M Grade:

Clock Start/From:

Clock To:

1st Value:

2nd Value:

MGO

Value Percent:
Step: NO
Remarks: access mh

Wednesday, May 3, 2023 2

Code:



Code: SRI

Description: Surface Roughness Increased

Distance (ft): .0
Structural Grade: 1
O&M Grade: 0
Clock Start/From: 12
Clock To: 12
1st Value:

2nd Value: Value Percent:

Step: NO

Remarks:



Code: MGO

Description: General Observation

Distance (ft): 2.1
Structural Grade: 0
O&M Grade: 0
Clock Start/From:
Clock To:

1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: underside of frame



Code: **DSF**

Description: Deposits Settled Fine

Distance (ft): 4.8
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 12
Clock To: 12
1st Value:

2nd Value:

Value Percent: 5.000 Step: NO

Remarks:

Wednesday, May 3, 2023 3



Code: SRI

Description: Surface Roughness Increased

Distance (ft): 4.8
Structural Grade: 1

O&M Grade: 0

Clock Start/From: 12

Clock To: 12

1st Value:

2nd Value: Value Percent:

Step: NO

Remarks:



Code: SRI

Description: Surface Roughness Increased

Distance (ft): 4.8
Structural Grade: 1
O&M Grade: 0
Clock Start/From: 12
Clock To: 12
1st Value:
2nd Value:

Step: NO

Remarks:

Value Percent:



Code: SAV

Description: Surface Aggregate Visible

Distance (ft): 4.8
Structural Grade: 3
O&M Grade: 0
Clock Start/From: 3
Clock To: 9
1st Value:
2nd Value:
Value Percent:

Step: NO

Remarks:

Wednesday, May 3, 2023