Manhole Inspection Report



Date: 11/07/2022 Weather: Coding: RZMACP

MH#: M-708-168 Owner: NA Len. Surveyed: 3.4
P.O.#: Surveyor: Jen Costello Rim to Invert: 4.2

Customer: Cert. #: U-907-5518 Wall Material: Concrete (non-

reinforced)

Street: Azalea Dr. Magnolia Dr. to the West. Project: Missing GPS

City: Hobart, IN GPS Northing: 2280325.156
Location: GPS Easting: 2905779.507

Drain Area: Southwest GPS Accuracy: Sub-Meter

Cover Shape: Circular Evidence of Surcharge: No
Cover Size: 24.0 Potential for Runoff: None

Comments:

2.00 2100 2.00 O&M Index: O&M Quick: O&M Rating: 1.00 1400 4.00 Structural Index: Structural Quick: Structural Rating: 1.20 2114 6.00 Overall Index: Overall Quick: Overall Rating:

Wednesday, May 3, 2023

.0 SRI Surface Roughness Increased 10 S1 .0 MGO General Observation 21 NA .7 MGO General Observation 36 NA 3.4 DSF Deposits Settled Fine 54 M2 3.4 SRI Surface Roughness Increased 66 S1 3.4 SRI Surface Roughness Increased 77 S1 3.4 MGO General Observation 88 NA	Positio	n Code	Observation	Video (sec)	Grade
.0 SRI Surface Roughness Increased 10 S 1 .0 MGO General Observation 21 NA .7 MGO General Observation 36 NA 3.4 DSF Deposits Settled Fine 54 M 2 3.4 SRI Surface Roughness Increased 66 S 1 3.4 SRI Surface Roughness Increased 77 S 1	08-168				
.7 MGO General Observation 36 NA 3.4 DSF Deposits Settled Fine 54 M 2 3.4 SRI Surface Roughness Increased 66 S 1 3.4 SRI Surface Roughness Increased 77 S 1	<i>1</i> .	SRI	Surface Roughness Increased	10	S 1
3.4 DSF Deposits Settled Fine 54 M 2 3.4 SRI Surface Roughness Increased 66 S 1 3.4 SRI Surface Roughness Increased 77 S 1	\0	MGO	General Observation	21	NA
3.4 SRI Surface Roughness Increased 66 S 1 3.4 SRI Surface Roughness Increased 77 S 1	.7	MGO	General Observation	36	NA
3.4 SRI Surface Roughness Increased 77 S 1	/3.4	DSF	Deposits Settled Fine	54	M 2
	3.4	SRI	Surface Roughness Increased	66	S 1
3.4 MGO General Observation 88 NA	3.4	SRI	Surface Roughness Increased	77	S 1
	3.4	MGO	General Observation	88	NΔ
				30	



Description:	Surface Roughness Increased
Distance (ft):	.0
Structural Grade:	1
O&M Grade:	0
Clock Start/From:	12
Clock To:	12
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	

SRI

Wednesday, May 3, 2023 2

Code:



Code: MGO

Description: General Observation

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: access mh



Code: MGO

Description: General Observation

Distance (ft): .7
Structural Grade: 0

O&M Grade: 0

Clock Start/From:
Clock To:
1st Value:
2nd Value:

Step: NO

Value Percent:

Remarks: underside of frame



Code: **DSF**

Description: Deposits Settled Fine

Distance (ft): 3.4
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 12
Clock To: 12
1st Value:

Value Percent: 5.000 Step: NO

Remarks:

2nd Value:

Wednesday, May 3, 2023



Code: SRI

Description: Surface Roughness Increased

Distance (ft): 3.4
Structural Grade: 1

O&M Grade: 0

Clock Start/From: 3

Clock To: 9

1st Value:

2nd Value: Value Percent:

Step: NO

Remarks:



Code: SRI

Description: Surface Roughness Increased

Distance (ft): 3.4
Structural Grade: 1
O&M Grade: 0
Clock Start/From: 12
Clock To: 12
1st Value:
2nd Value:

Step: NO

Remarks:

2nd Value: Value Percent:

Value Percent:



Code: MGO

Description: General Observation

Distance (ft): 3.4
Structural Grade: 0

O&M Grade: 0

Clock Start/From:
Clock To:
1st Value:

Step: NO

Remarks: end of survey

Wednesday, May 3, 2023 4