Manhole Inspection Report



Date:

Customer:

04/12/2018

Weather:

Coding: **RZMACP**

MH#:

M-709-013

Owner:

Len. Surveyed:

P.O.#:

Surveyor: Cert. #:

John Kuglmaier U-1215-07002349 Rim to Invert: Wall Material:

Concrete

(reinforced)

10.5

12.2

Street: City:

Dunlin Circle. Southeast Corner.

Project:

Hobart, IN

Hobart, IN

GPS Northing:

NA

2906604.552

Location:

GPS Easting:

2906604.552

Drain Area:

Southwest

GPS Accuracy:

Sub-Meter

Cover Shape:

Circular

22.5

Evidence of Surcharge: No

Cover Size:

Comments:

Potential for Runoff:

None

O&M Index:

0.00 0.00

O&M Quick: Structural Quick:

0000 0000 0000

O&M Rating: Structural Rating:

Overall Rating:

0.00 0.00 0.00

Structural Index: Overall Index:

0.00 Overall Quick:

Wednesday, May 3, 2023

1

Р	osition	Code	Observation	Video (sec)	Grade
M-709-013					
.0)	MGP	General Photo	10	NA
2.	8	MGP	General Photo	29	NA
4.	7	IS	Infil Stain	47	NA
9.	8	MGO	General Observation	69	NA
/					
g					
Camera Direction					
Dir.					
e ra					
me .					
+					
- 111					
- 111					
- 111					
- 111					
- 111					
100					
	ı				

Code:



Description:	General Photo
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	

MGP

Wednesday, May 3, 2023



Code: MGP

Description: General Photo

Distance (ft): 2.8
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks:



Code: IS

Description: Infil Stain

Distance (ft): 4.7
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 2
Clock To: 3
1st Value:
2nd Value:
Value Percent:

Step: NO

Remarks:



Code: MGO

Description: General Observation

Distance (ft): 9.8
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: Ins. Comp.

Wednesday, May 3, 2023 3