Manhole Inspection Report



Date:

04/12/2018

Weather:

RZMACP

MH#:

M-709-014

Owner:

NA

Len. Surveyed: 10.6 10.9 Rim to Invert:

P.O.#:

Customer:

Surveyor: John Kuglmaier U-1215-07002349 Cert. #:

Wall Material:

Coding:

Concrete (reinforced)

Street: City:

Dunlin Circle. South Side.

Project: **GPS Northing:**

Hobart, IN 2906441.261

Location:

Hobart, IN

2906441.261

Drain Area:

Southwest

GPS Easting:

Sub-Meter

Cover Shape:

Circular

GPS Accuracy: Evidence of Surcharge: No

Cover Size:

22.5

Potential for Runoff:

None

Comments:

O&M Index:

0.00

0.00 O&M Quick: Structural Quick:

0000 0000 0000

O&M Rating: Structural Rating: Overall Rating:

0.00 0.00 0.00

Structural Index: Overall Index:

0.00 Overall Quick:

Wednesday, May 3, 2023

Position	Code	Observation	Video (sec)	Grade
M-709-014				
.0	MGP	General Photo	10	NA
1.2	IS	Infil Stain	24	NA
2.5	MGP	General Photo	40	NA
/8.6	MGO	General Observation	66	NA
Camera Direction				
t				
출				
e l				
ž III				
2				
*				
111				
- 11				
- 11				
- 11				
- 11				

Code:



Description:	General Photo
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	

MGP

Wednesday, May 3, 2023 2



Code: IS

Description: Infil Stain

Distance (ft): 1.2
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 10
Clock To: 2
1st Value:

2nd Value: Value Percent:

Step: NO

Remarks:



Code: MGP

Description: General Photo

Distance (ft): 2.5
Structural Grade: 0
O&M Grade: 0
Clock Start/From:
Clock To:
1st Value:

2nd Value: Value Percent:

Step: NO

Remarks:



Code: MGO

Description: General Observation

Distance (ft): 8.6
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: Ins. Comp.

Wednesday, May 3, 2023 3