## **Manhole Inspection Report**



Date: 11/01/2022 Weather: Coding: RZMACP

 MH#:
 M-709-028
 Owner:
 NA
 Len. Surveyed:
 9.3

 P.O.#:
 Surveyor:
 Jen Costello
 Rim to Invert:
 10.6

Customer: Cert. #: U-907-5518 Wall Material: Concrete (non-

reinforced)

Street:Avocet Circle. the East Side.Project:Missing GPSCity:Hobart, INGPS Northing:2279256.908

Location: GPS Easting: 2906820.845

Drain Area: Southwest GPS Accuracy: Sub-Meter

Cover Shape: Circular Evidence of Surcharge: No
Cover Size: 24.0 Potential for Runoff: None

Comments:

O&M Index:	2.00	O&M Quick:	2100	O&M Rating:	2.00
Structural Index:	1.00	Structural Quick:	1A00	Structural Rating:	10.00
Overall Index:	1.09	Overall Quick:	211A	Overall Rating:	12.00

Wednesday, May 3, 2023

	Code	Observation	Video (sec)	Grade
09-028				
.0	SRI	Surface Roughness Increased	10	S 1
0.	MGO	General Observation	21	NA
2.9	MGO	General Observation	40	NA
9.3	SRI	Surface Roughness Increased	67	S 1
9.3	MGO	General Observation	78	NA
9.3	SRI	Surface Roughness Increased	89	S 1
9.3	DSF	Deposits Settled Fine	100	M 2



Description:	Surface Roughness Increased		
Distance (ft):	.0		
Structural Grade:	1		
O&M Grade:	0		
Clock Start/From:	12		
Clock To:	12		
1st Value:			
2nd Value:			
Value Percent:			
Step:	NO		
Remarks:			

SRI

Wednesday, May 3, 2023

Code:



Code: MGO

Description: General Observation

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To:

1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: access mh



Code: MGO

Description: General Observation

Distance (ft): 2.9
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To:
1st Value:
2nd Value:
Value Percent:

Step: NO

Remarks: underside of frame



Code: SRI

Description: Surface Roughness Increased

Distance (ft): 9.3
Structural Grade: 1
O&M Grade: 0
Clock Start/From: 12
Clock To: 12
1st Value:
2nd Value:
Value Percent:

Step: NO

Remarks:

Wednesday, May 3, 2023



Code: MGO

Description: General Observation

Distance (ft): 9.3
Structural Grade: 0
O&M Grade: 0

Clock Start/From: Clock To:

1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: end of survey



Code: SRI

Description: Surface Roughness Increased

Distance (ft): 9.3
Structural Grade: 1
O&M Grade: 0
Clock Start/From: 3
Clock To: 9
1st Value:
2nd Value:

Step: NO

Remarks:

Code:

Value Percent:



DSF

Description: Deposits Settled Fine

Distance (ft): 9.3
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 12
Clock To: 12
1st Value:

2nd Value:
Value Percent: 5.000
Step: NO

Remarks:

Wednesday, May 3, 2023 4