Manhole Inspection Report



Date: 11/01/2022 Weather: Coding: RZMACP

 MH#:
 M-709-034
 Owner:
 NA
 Len. Surveyed:
 5.8

 P.O.#:
 Surveyor:
 Jen Costello
 Rim to Invert:
 6.7

Customer: Cert. #: U-907-5518 Wall Material: Concrete (non-

reinforced)

Street: Waxwing Circle. West Side. Project: 502259S9MACP26Jan2023

 City:
 Hobart, IN
 GPS Northing:
 2278807.89

 Location:
 GPS Easting:
 2906436.101

Drain Area: Southwest GPS Accuracy: Sub-Meter

Cover Shape: Circular Evidence of Surcharge: No
Cover Size: 24.0 Potential for Runoff: None

Comments:

O&M Index:	2.75	O&M Quick:	5123	O&M Rating:	11.00
Structural Index:	1.00	Structural Quick:	1600	Structural Rating:	6.00
Overall Index:	1.70	Overall Quick:	5123	Overall Rating:	17.00

Wednesday, May 3, 2023

Code	Observation	Video (sec)	Grade
SRI	Surface Roughness Increased	10	S 1
MGO	General Observation	22	NA
MGO	General Observation	39	NA
ОВР	Obstacle External Pipe or Cable	52	M 2
IW	Infil Weeper	68	M 2
DSF	Deposits Settled Fine	83	M 2
MGO	General Observation	94	NA
SRI	Surface Roughness Increased	105	S 1
DSF	Deposits Settled Fine	117	M 5
	MGO MGO OBP IW DSF MGO SRI	MGO General Observation MGO General Observation OBP Obstacle External Pipe or Cable IW Infil Weeper DSF Deposits Settled Fine MGO General Observation SRI Surface Roughness Increased	MGOGeneral Observation22MGOGeneral Observation39OBPObstacle External Pipe or Cable52IWInfil Weeper68DSFDeposits Settled Fine83MGOGeneral Observation94SRISurface Roughness Increased105



Description:	Surface Roughness Increased		
Distance (ft):	.0		
Structural Grade:	1		
O&M Grade:	0		
Clock Start/From:	12		
Clock To:	12		
1st Value:			
2nd Value:			
Value Percent:			
Step:	NO		
Remarks:			

SRI

Wednesday, May 3, 2023

Code:



Code: MGO

Description: General Observation

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: access mh



Code: MGO

Description: General Observation

Distance (ft): 1.9
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: underside of frame



Code: OBP

Description: Obstacle External Pipe or Cable

Distance (ft): 1.9
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 12
Clock To: 6
1st Value:

2nd Value:

Value Percent: 5.000
Step: NO
Remarks:

Wednesday, May 3, 2023 3



Code: IW


Description: Infil Weeper

Distance (ft): 3.9
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 12
Clock To: 12

1st Value: 2nd Value: Value Percent:

Step: NO

Remarks:



Code: **DSF**

Description: Deposits Settled Fine

Distance (ft): 5.8
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 12
Clock To: 12
1st Value:

Value Percent: 5.000 Step: NO

Remarks:

2nd Value:



Code: MGO

Description: General Observation

Distance (ft): 5.8
Structural Grade: 0
O&M Grade: 0
Clock Start/From:
Clock To:
1st Value:
2nd Value:

Step: NO

Value Percent:

Remarks: end of survey

Wednesday, May 3, 2023



Code: SRI

Description: Surface Roughness Increased

Distance (ft): 5.8
Structural Grade: 1
O&M Grade: 0
Clock Start/From: 12
Clock To: 12
1st Value:
2nd Value:

Value Percent: Step: NO

Remarks:



Code: **DSF**

Description: Deposits Settled Fine

Distance (ft): 5.8
Structural Grade: 0
O&M Grade: 5
Clock Start/From: 4
Clock To: 8
1st Value:

Value Percent: 40.000 Step: NO

5

Remarks:

2nd Value:

Wednesday, May 3, 2023