Manhole Inspection Report



Date: 04/12/2018

Weather:

Coding:

RZMACP

MH#:

M-802-005

Owner: NA

Len. Surveyed: 4.5 Rim to Invert:

P.O.#:

John Kuglmaier Surveyor: U-1215-07002349 Cert. #:

Wall Material:

Concrete

(reinforced)

5.5

Street: City:

Customer:

Wisconsin St. 29' North of 40th Plac Project:

Hobart, IN

Location:

Hobart, IN

GPS Northing:

2909639.089

Drain Area:

Northwest

GPS Easting: GPS Accuracy: 2909639.089 **Sub-Meter**

Cover Shape: Cover Size:

Circular

23.0

Evidence of Surcharge:

Yes Potential for Runoff:

None

Comments:

O&M Index:

Overall Quick:

2100 O&M Rating:

2.00 0.00

2.00

Structural Index: Overall Index:

2.00 O&M Quick: 0.00 Structural Quick:

2.00

0000 Structural Rating: 2100 Overall Rating:

Wednesday, May 3, 2023

1

	Position	Code	Observation	Video (sec)	Grade
M-802-00	5				
	.0	MGP	General Photo	10	NA
- 11	2.2	DSF	Deposits Settled Fine	26	M 2
- 11	2.4	MGP	General Photo	40	NA
- 11	3.8	MGO	General Observation	57	NA
Camera Direction					



Distance (ft):	.0	
Structural Grade:	0	
O&M Grade:	0	
Clock Start/From:		
Clock To:		
1st Value:		
2nd Value:		
Value Percent:		
Step:	NO	
Remarks:		


MGP

General Photo

Wednesday, May 3, 2023 2

Code:

Description:



DSF Code:

Description: **Deposits Settled Fine**

Distance (ft): 2.2 Structural Grade: 0 O&M Grade: 2 Clock Start/From: 12 Clock To: 12 1st Value:

2nd Value:

5.000 Value Percent: Step: NO

Remarks:



Code: MGP

Description: **General Photo**

Distance (ft): 2.4 Structural Grade: 0 O&M Grade: 0 Clock Start/From: Clock To: 1st Value:

2nd Value: Value Percent: Step:

NO

Remarks:



Code: MGO

General Observation Description:

Distance (ft): 3.8 Structural Grade: 0 O&M Grade: 0 Clock Start/From: Clock To: 1st Value:

2nd Value: Value Percent:

Step: NO

Remarks: Ins. Comp.