
Date:	03/21/2018	Weather:		Coding:	RZMACP
MH#:	M-802-019	Owner:	NA	Len. Surveyed:	4.8
P.O.#:		Surveyor:	John Kuglmaier	Rim to Invert:	5.7
Customer:		Cert. #:	U-1215-07002349	Wall Material:	Concrete (reinforced)
Street:	North of Hwy 6. 46	'West of North R	Project:	Hobart, IN	
City:	Hobart, IN	(	GPS Northing:	0.0	
Location:		(	GPS Easting:	0.0	
Drain Area:	Northeast	(	GPS Accuracy:	Nearest Meter	
Cover Shape:	Circular	E	Evidence of Surcharge:	Yes	
Cover Size: Comments:	23.0	F	Potential for Runoff:	None	
O&M Index:	0.00	O&M Quick:	0000	O&M Rating:	0.00
Structural Index:	0.00	Structural Quic	ck: 0000	Structural Rating:	0.00
Overall Index:	0.00	Overall Quick:	0000	Overall Rating:	0.00

Position	Code	Observation	Video (sec)	Grade
1-802-019				
0.	MGP	General Photo	10	NA
1.8	IS	Infil Stain	26	NA
2.3	MGP	General Photo	41	NA
4.1	MGO	General Observation	58	NA
Camera Direction				




Code:	MGP
Description:	General Photo
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	



Code:	IS
Description:	Infil Stain
Distance (ft):	1.8
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	8
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	


Step:

Remarks:



Code: Description:	MGP General Photo
Distance (ft): Structural Grade: O&M Grade: Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Step:	2.3 0 0
Remarks:	

NO



Code: Description:	MGO General Observation
·	
Distance (ft):	4.1
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	Ins. Comp.