Manhole Inspection Report



Date: 03/22/2018 Weather: Coding: RZMACP

 MH#:
 M-802-022
 Owner:
 NA
 Len. Surveyed:
 4.9

 P.O.#:
 Surveyor:
 John Kuglmaier
 Rim to Invert:
 5.7

Customer: Cert. #: U-1215-07002349 Wall Material: Concrete

(reinforced)

Street: 779' North of Hwy 6. 620' West of H Project: Hobart, IN

City: Hobart, IN GPS Northing: 0.0

Location: GPS Easting: **0.0**

Drain Area: Northeast GPS Accuracy: Nearest Meter

Cover Shape: Circular Evidence of Surcharge: Yes

Cover Size: 23.0 Potential for Runoff: None

Comments:

O&M Index:	3.00	O&M Quick:	3100	O&M Rating:	3.00
Structural Index:	0.00	Structural Quick:	0000	Structural Rating:	0.00
Overall Index:	3.00	Overall Quick:	3100	Overall Rating:	3.00

Wednesday, May 3, 2023

ı	Position	Code	Observation	Video (sec)	Grade
-802-022					
· /.	0	MGP	General Photo	10	NA
1	l.9	MGP	General Photo	28	NA
[2	2.6	DAZ	Deposits Attached Other	43	M 3
	1.0	MGO	General Observation	57	NA
ш					
ш					
Ш					
ш					
11					
ш					
ш					
	_				



Description:	General Photo		
Distance (ft):	.0		
Structural Grade:	0		
O&M Grade:	0		
Clock Start/From:			
Clock To:			
1st Value:			
2nd Value:			
Value Percent:			
Step:	NO		
Remarks:			

MGP

Wednesday, May 3, 2023 2

Code:



Code: MGP

Description: General Photo

Distance (ft): 1.9
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks:

2nd Value:



Code: DAZ

Description: Deposits Attached Other

Distance (ft): 2.6
Structural Grade: 0
O&M Grade: 3
Clock Start/From: 12
Clock To: 12
1st Value:

Value Percent: 15.000 Step: NO

Remarks: Mixed materials



Code: MGO

Description: General Observation

Distance (ft): 4.0
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To:
1st Value:
2nd Value:
Value Percent:

Step: NO

Remarks: Ins. Comp.

Wednesday, May 3, 2023 3