## **Manhole Inspection Report**



Date: 03/21/2018 Weather: Coding: RZMACP

 MH#:
 M-802-023
 Owner:
 NA
 Len. Surveyed:
 1.7

 P.O.#:
 Surveyor:
 John Kuglmaier
 Rim to Invert:
 3.0

Customer: Cert. #: U-1215-07002349 Wall Material: Concrete

(reinforced)

Street: 177' North of Hwy 6. 97' West of No Project: Hobart, IN

City: Hobart, IN GPS Northing: 0.0 Location: GPS Easting: 0.0

Drain Area: Northeast GPS Accuracy: Nearest Meter

Cover Shape: Circular Evidence of Surcharge: No
Cover Size: 23.0 Potential for Runoff: None

Comments:

O&M Index:	2.00	O&M Quick:	2100	O&M Rating:	2.00
Structural Index:	0.00	Structural Quick:	0000	Structural Rating:	0.00
Overall Index:	2.00	Overall Quick:	2100	Overall Rating:	2.00

Wednesday, May 3, 2023

Code	Observation	Video (sec)	Grade
MGP	General Photo	10	NA
DAGS	Deposits Attached Grease	22	M 2
DAGS	Deposits Attached Grease	37	M 2
MSA	Abandoned Survey	49	NA
	DAGS DAGS	DAGS Deposits Attached Grease  DAGS Deposits Attached Grease	DAGS Deposits Attached Grease 22 DAGS Deposits Attached Grease 37



Description:	General Photo
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	

MGP

Wednesday, May 3, 2023

Code:



Code: DAGS

Description: Deposits Attached Grease

Distance (ft): .0
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 12
Clock To: 12
1st Value:

1st Value: 2nd Value:

Value Percent: 5.000 Step: NO

Remarks:



Code: DAGS

Description: Deposits Attached Grease

Distance (ft): 1.4
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 12
Clock To: 12
1st Value:

Value Percent: 5.000 Step: NO

Remarks:

2nd Value:

Code: MSA

Description: Abandoned Survey



Distance (ft): 1.6
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: Unknown

Wednesday, May 3, 2023