Manhole Inspection Report



Date: 03/27/2018 Weather: Coding: RZMACP

MH#: M-803-005 Owner: NA Len. Surveyed: 8.7
P.O.#: Surveyor: John Kuglmaier Rim to Invert: 11.0

U-1215-07002349

Wall Material: Concrete (reinforced)

Street: 165' North of High St. 165' East of Li Project: Hobart, IN

Cert. #:

City: Hobart, IN GPS Northing: 0.0

Location: GPS Easting: **0.0**

Drain Area: Northeast GPS Accuracy: Nearest Meter

Cover Shape: Circular Evidence of Surcharge: Yes
Cover Size: 23.0 Potential for Runoff: None

Comments:

Customer:

O&M Index:	2.00	O&M Quick:	2100	O&M Rating:	2.00
Structural Index:	0.00	Structural Quick:	0000	Structural Rating:	0.00
Overall Index:	2.00	Overall Quick:	2100	Overall Rating:	2.00

Wednesday, May 3, 2023

Position	Code	Observation	Video (sec)	Grade
M-803-005				
.0	MGP	General Photo	10	NA
2.3	MGP	General Photo	28	NA
6.6	DSF	Deposits Settled Fine	51	M 2
7.7	MGO	General Observation	64	NA
Camera Direction				



Description: **General Photo** Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Step: NO Remarks:

MGP

Wednesday, May 3, 2023 2

Code:



Code: MGP

Description: General Photo

Distance (ft): 2.3
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks:



Code: **DSF**

Description: Deposits Settled Fine

Distance (ft): 6.6
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 12
Clock To: 6
1st Value:

Value Percent: 5.000 Step: NO

Remarks:

2nd Value:



Description: General Observation



Distance (ft): 7.7
Structural Grade: 0

O&M Grade: **0**

Clock Start/From: Clock To:

1st Value: 2nd Value:

Value Percent:

Step: NO

Remarks: Ins. Comp.

Wednesday, May 3, 2023 3