Manhole Inspection Report



Date:

03/28/2018

Weather:

NA

Coding:

RZMACP

12.3

14.4

MH#:

M-803-010

Owner:

Len. Surveyed: Rim to Invert:

P.O.#:

Surveyor: Cert. #:

John Kuglmaier U-1215-07002349

Wall Material:

Concrete

Street:

Customer:

341' South of Rand St. 163' East of L Project:

(reinforced)

City:

Hobart, IN

GPS Northing:

Hobart, IN 0.0

Location:

GPS Easting:

0.0

Drain Area: Cover Shape: Northeast

GPS Accuracy:

Nearest Meter

Cover Size:

Circular

23.0

Evidence of Surcharge: Potential for Runoff:

Yes None

Comments:

O&M Index:

0.00

2.00 O&M Quick: Structural Quick:

2100 0000 2100

O&M Rating: Structural Rating:

Overall Rating:

2.00 0.00 2.00

Structural Index: Overall Index:


2.00 Overall Quick:

Wednesday, May 3, 2023

1

Position	Code	Observation	Video (sec)	Grade
M- 803-0 10				
.0	MGP	General Photo	10	NA
2.1	MGP	General Photo	28	NA
10.4	DAZ	Deposits Attached Other	58	M 2
11.6	MGO	General Observation	72	NA
Camera Direction				

Code:



Description: **General Photo** Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Step: NO Remarks:

MGP



Code: MGP

Description: General Photo

Distance (ft): 2.1
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks:



Code: DAZ

Description: Deposits Attached Other

Distance (ft): 10.4
Structural Grade: 0

O&M Grade: 2

Clock Start/From: 12

Clock To: 12

1st Value:

2nd Value:

Value Percent: 10.000 Step: NO

Remarks: Mixed materials



Code: MGO

Description: General Observation

Distance (ft): 11.6
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: Ins. Comp.

3