## **Manhole Inspection Report**



Date:

Customer:

03/28/2018

Weather:

Coding: **RZMACP** 

MH#:

M-803-045

Owner:

Len. Surveyed: 15.0 16.5

P.O.#:

John Kuglmaier Surveyor: U-1215-07002349 Cert. #:

NA

Rim to Invert: Wall Material:

Concrete (reinforced)

Street: City:

High St. 163' East of Kelly St.

Project:

Hobart, IN

Hobart, IN

**GPS Northing:** 

0.0 0.0

Location: Drain Area:

Northeast

GPS Easting:

**Nearest Meter** 

Cover Shape: Cover Size:

Circular

GPS Accuracy: Evidence of Surcharge:

23.0

Potential for Runoff:

0000

Yes None

Comments:

O&M Index: Structural Index:

Overall Index:

0.00 0.00

0.00

O&M Quick:

Structural Quick: Overall Quick:

0000 O&M Rating: 0000 Structural Rating:

Overall Rating:

0.00 0.00

0.00

Position	Code	Observation	Video (sec)	Grade
л- <mark>803-0</mark> 45				
.0	MGP	General Photo	10	NA
2.1	MGP	General Photo	28	NA
13.3	MGO	General Observation	64	NA
Camera Direction				



Description:	General Photo	
Distance (ft):	.0	
Structural Grade:	0	
O&M Grade:	0	
Clock Start/From:		
Clock To:		
1st Value:		
2nd Value:		
Value Percent:		
Step:	NO	
Remarks:		

MGP

Wednesday, May 3, 2023

Code:



Code: MGP

Description: General Photo

Distance (ft): 2.1
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks:



Code: MGO

Description: General Observation

Distance (ft): 13.3
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: Ins. Comp.

Wednesday, May 3, 2023