Date:	05/07/2018	Weather:		Coding:	RZMACP
MH#:	M-804-007	Owner:	NA	Len. Surveyed:	6.2
P.O.#:		Surveyor:	Jen Costello	Rim to Invert:	6.5
Customer:		Cert. #:	U-907-5518	Wall Material:	Brick
Street:	Hwy 51. 171' North of Cleveland Ave Project:		Hobart, IN		
City:	Hobart, IN	(GPS Northing:	2909741.074	
Location:		(GPS Easting:	2909741.074	
Drain Area:	South	(GPS Accuracy:	Sub-Meter	
Cover Shape:	Circular	I	Evidence of Surcharge:	No	
Cover Size:	22.5	Potential for Runoff:		None	
Comments:					
O&M Index:	2.00	O&M Quick:	2200	O&M Rating:	4.00
Structural Index:	4.00	Structural Quid	ck: 4100	Structural Rating:	4.00
Overall Index:	2.67	Overall Quick:	4122	Overall Rating:	8.00

Position	Code	Observation	Video (sec)	Grade
304-007				
.0	MGP	General Photo	10	NA
.8	MB	Missing Brick	23	S 4
2.4	MGO	General Observation	40	NA
4.4	DSF	Deposits Settled Fine	57	M 2
4.4	OBR	Obstacle Rocks	69	M 2
6.2	MGO	General Observation	84	NA



MGP
General Photo
_
.0
0
0
NO
ACCESS MH



Code: Description:	MB Missing Brick
	-
Distance (ft):	.8
Structural Grade:	4
O&M Grade:	0
Clock Start/From:	10
Clock To:	3
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	



Code: Description:	MGO General Observation
Distance (ft): Structural Grade: O&M Grade: Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Step:	2.4 0 0
Remarks:	UNDERSIDE OF FRAME



Code: Description:	DSF Deposits Settled Fine
Distance (ft):	4.4
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	12
Clock To:	12
1st Value:	
2nd Value:	
Value Percent:	5.000
Step:	NO
Remarks:	



Code: Description:	OBR Obstacle Rocks
Description	
Distance (ft):	4.4
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	12
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	5.000
Step:	NO
Remarks:	



Code:	MGO
Description:	General Observation
Distance (ft):	6.2
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	END SURVEY