Manhole Inspection Report



Date:

05/15/2018

Weather:

Coding: **RZMACP**

MH#:

M-804-031

Owner: NA Len. Surveyed:

P.O.#:

Surveyor: Cert. #:

Jen Costello U-907-5518

Rim to Invert: Wall Material:

10.0 Concrete

(reinforced)

8.9

Street: City:

Customer:

33' South of Hickey St. 173' West of Project:

GPS Northing:

Hobart, IN 2909563.854

Location:

Hobart, IN

GPS Easting:

2909563.854

Drain Area:

Northeast

Sub-Meter

Cover Shape: Cover Size:

Circular

GPS Accuracy: Evidence of Surcharge: No

22.5

Potential for Runoff: None

0000

Comments:

O&M Index:

0.00 O&M Quick:

O&M Rating:

0.00 0.00

0.00

Structural Index: Overall Index:

0.00 Structural Quick: 0.00 Overall Quick:


0000 Structural Rating: 0000 Overall Rating:

Wednesday, May 3, 2023

1

Position	Code	Observation	Video (sec)	Grade
M-804-031				
.0	MGP	General Photo	10	NA
1.9	MGO	General Observation	27	NA
8.9	MGO	General Observation	54	NA
Camera Direction				

Code:



Description:	General Photo
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	ACCESS MH

MGP

Wednesday, May 3, 2023 2



Code: MGO

Description: General Observation

Distance (ft): 1.9
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: UNDERSIDE OF FRAME



Code: MGO

Description: General Observation

Distance (ft): 8.9
Structural Grade: 0
O&M Grade: 0

Clock Start/From: Clock To:

1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: END SURVEY

Wednesday, May 3, 2023 3