Date:	03/27/2018	Weather:		Coding:	RZMACP
MH#:	M-804-051	Owner:	NA	Len. Surveyed:	5.0
P.O.#:		Surveyor:	John Kuglmaier	Rim to Invert:	6.0
Customer:		Cert. #:	U-1215-07002349	Wall Material:	Concrete (reinforced)
Street:	Ohio St. and High St. to the South.		Project:	Hobart, IN	
City:	Hobart, IN		GPS Northing:	0.0	
Location:			GPS Easting:	0.0	
Drain Area:	Northeast		GPS Accuracy:	Nearest Meter	
Cover Shape:	Circular		Evidence of Surcharge:	No	
Cover Size: Comments:	23.0		Potential for Runoff:	None	
O&M Index:	2.00	O&M Quick:	2100	O&M Rating:	2.00
Structural Index:	0.00	Structural Qu	ick: 0000	Structural Rating:	0.00
Overall Index:	2.00	Overall Quick		Overall Rating:	2.00

M-804-051       .0     MGP     General Photo       2.1     MGP     General Photo       2.7     DSF     Deposits Settled Fine       4.0     MGO     General Observation	10 N/ 28 N/ 43 M 57 N/
.0   MGP   General Photo     2.1   MGP   General Photo     2.7   DSF   Deposits Settled Fine     4.0   MGO   General Observation	28 NA 43 M
2.7 DSF Deposits Settled Fine   4.0 MGO General Observation	43 M
4.0 MGO General Observation	
	57 N/



Code:	MGP
Description:	General Photo
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	



Code: Description: D S C C C

MGP **General Photo** 

Distance (ft):	2.1	
Structural Grade:	0	
O&M Grade:	0	
Clock Start/From:		
Clock To:		
1st Value:		
2nd Value:		
Value Percent:		
Step:	NO	
Remarks:		

Code:



Description:	Deposits Settled Fine
Distance (ft):	2.7
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	12
Clock To:	12
1st Value:	
2nd Value:	
Value Percent:	5.000
Step:	NO
Remarks:	

DSF



MGO
General Observation
4.0
4.0
0
0
NO
Ins. Comp.