Manhole Inspection Report



Date: 05/15/2018 Coding: Weather: MH#: M-804-067 Owner: NA

Len. Surveyed: 8.4 P.O.#: Surveyor: Jen Costello Rim to Invert: 8.7

Customer: Cert. #: U-907-5518 Wall Material: Concrete

(reinforced)

RZMACP

Hwy 51. 126' South of High St. Street: City:

Hobart, IN Project: Hobart, IN GPS Northing: 2909740.948

Location: GPS Easting: 2909740.948

Drain Area: Northeast **GPS Accuracy:** Sub-Meter Cover Shape: Circular Evidence of Surcharge: No

22.5 Potential for Runoff: Cover Size: None

Comments:

O&M Index:	2.50	O&M Quick:	3121	O&M Rating:	5.00
Structural Index:	0.00	Structural Quick:	0000	Structural Rating:	0.00
Overall Index:	2.50	Overall Quick:	3121	Overall Rating:	5.00

1 Wednesday, May 3, 2023

	Code	Observation	Video (sec)	Grade
-804-067				
.0	MGP	General Photo	10	NA
1.4	MGO	General Observation	26	NA
3.8	IW	Infil Weeper	44	M 2
8.4	OBR	Obstacle Rocks	65	M 3
8.4	MGO	General Observation	76	NA



Description:	General Photo
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	ACCESS MH

MGP

Wednesday, May 3, 2023

Code:



Code: MGO

Description: General Observation

Distance (ft): 1.4
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:

Step: NO

Remarks: UNDERSIDE OF FRAME



Code: IW

Description: Infil Weeper

Distance (ft): 3.8
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 12
Clock To: 2
1st Value:
2nd Value:

Step: NO

Remarks:

Value Percent:



Code: OBR

Description: Obstacle Rocks

Distance (ft): 8.4
Structural Grade: 0
O&M Grade: 3
Clock Start/From: 3
Clock To: 9
1st Value:

2nd Value:

Value Percent: 20.000 Step: NO

Remarks:

Wednesday, May 3, 2023



Code: MGO

Description: General Observation

Distance (ft): 8.4
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: END SURVEY

Wednesday, May 3, 2023